

कार्यपालक अभियंता, का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सीतामढ़ी

पत्रांक ७४४अड/ दिनांक ०५-७-२४

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सीतामढ़ी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय:-

शीर्ष बिहार नई अनुरक्षण नीति 2018 (MR 3054) में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषयक इस प्रमंडल अंतर्गत चल रहे नई अनुरक्षण नीति 2018 (MR 3054) में स्वीकृत योजनाओं के विभिन्न कार्यों के लिए संलग्न विवरणी अनुसार भुगतान हेतु आवंटन उपलब्ध कराने की कृपा की जाय।

अनु०:- यथोक्त।

विश्वासभाजन

Aw
०५/०७/२४

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सीतामढ़ी।

05/07/24

प्रमाण

Requisition Format for Scheme Head-MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division RWD, Works Division- Sitamarhi

Name of Works Division RWD, Works Division- Sitamarhi																			
Sl. No	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA) letter No. & Date	Length (in KM)	Administrative Approval (AA)			Agreement Amount (in Lakh)		Agreement No. Date	Date of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to Date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
						Amount (in Lakh)	5 Years Routine Maintenance (in Lakh)	Initial Rectification With Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	MR-N/2023-24/ Sitamarhi/06	Sonbarsa to Bhurahi via Rajwara and Lokhar	316791899473	Lt. No.-3411 Dt.-28.06.23	22.400	2344.310	249.180	- 1883.79556	208.18376	64/ MBD/23-24	15.10.2024	3200	25mm	5.00%	0.000000	0.000000	421.57451		
					22.400	2344.310	249.180	1883.79556	208.18376						0.000000	0.000000	421.57451		

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed

2. Up-to date Physical Progress has been uploaded in MIS

[Signature]
02/07/24
Executive Engineer
RWD (M) Division,
Sitamarhi
[Signature]

FORM GFR 19-A

(See Government of India's Decision (1) below Rule 150)

Form of Utilization Certification up to the month of July 2024

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs Rs.)	Amount Received (in Rs.)	Particulars
1	Construction of Rural Road New Maintenance Policy 2018	Up to Date Received Allotment	Rs. 1867558542.00	Certified that out of Rs 1867558542.00 received during the years 2023-24 in favor of Executive Engineer Sitamarhi, Bihar a sum of Rs. 1855690939.00 has been utilized for the purpose of New Maintenance Policy 2018 Scheme as given in the margin for which it was sanctioned and that the balance of Rs 11867603.00 remaining unutilized at the end of the period under report
	Total:			

2. Certified that I have satisfied myself that the condition on which the grant-in-aid was sanctioned have been duly fulfilled /are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/Superintending
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer
- All other codal formalities

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works

Ani
02/07/24
Executive Engineer,
R.W.D. Works,
Division Sitamarhi.
19/05/24 *SPM*

Office of The Executive Engineer,
Rural Works Department, Works Division, Sitamarhi

Name of Road:-Sonbarsa to Bhutahi via Rajwara and Lokhar

Name of Scheme:- NEW MAINTENANCE POLICY

Name of Contractor:- MS/KABBU KHIRHAR

Length of Road:-22.4 KM

Project ID:- 316791899473

Package No.-RM/SI/SIT/24/03

Name of Block:-SONBARSA

Certified that all item wise
100% measurment has been
taken by me

Certified that all item wise 50%
measurment has been checked by
me

Certified that all item wise
10% measurment has been
checked by me


11/07/24
Junior Engineer,
Rural Works Department,
Works Section, Sonbarsa
Works Division, Sitamarhi


01/07/24
Assitant Engineer,
Rural Works Department,
Works Sub Division, Sonbarsa
Works Division, Sitamarhi


01/07/24
Executive Engineer,
Rural Works Department,
Works Division, Sitamarhi

Name of Customer :	M/S KABBU KIRIPPA
Name of Road :	Shahu via Ramwada and Lokhar
Lab Job number	114
Date :	01-07-2024
Section No.	43

Test Date :	01-07-2024	Road Name :	Shurahi via Paywara and Lohhar
Machine No :	396	Road Type :	(R) RURAL ROAD
Start S No :		Side :	
Start E No :		Interval	
Weather :		UIV Range :	11.25 To 5000 1000 mm/km
Start Location :		Dist Range :	0 To 71 01 1000 m
End Location :		Equation :	test


Print Generate Report and Graph

Redraw Graph

Map View

File : G:\virena kumari\02071958 - Copy.xls, Section No. : 43, Eqn : test

Name of Customer :M/S KABBU KHIRHAR, Name of Work/ Road :Sonbarsa to Bhutahi via Rajwara and Lokhar,



Richard J. Tinn

18 June
1972
72

26/6/2019

Dr
01/07/22

01/7/24	16:12:6	43	0.1	330	20.2	3300	3454	G	26.77845	85.60434	Normal						
01/7/24	16:12:6	43	0.1	260	10.1	2600	2679	G	26.7778	85.60369	Normal						
01/7/24	16:12:41	43	0.1	320	10.1	3200	3343	G	26.77697	85.60322	Normal						
01/7/24	16:13:0	43	0.1	330	20.2	3300	3454	G	26.77619	85.60281	Normal						
01/7/24	16:13:16	43	0.1	320	10.1	3200	3343	G	26.77535	85.60239	Normal						
01/7/24	16:13:16	43	0.1	330	20.2	3300	3454	G	26.77453	85.60197	Normal						
01/7/24	16:13:51	43	0.1	340	20.2	3400	3565	G	26.7737	85.6016	Curve						
01/7/24	16:14:0	43	0.1	330	20.2	3300	3454	G	26.77299	85.60096	Normal						
01/7/24	16:15:2	43	0.1	310	10.1	3100	3233	G	26.77228	85.60034	Normal						
01/7/24	16:15:37	43	0.1	320	20.2	3200	3343	G	26.77151	85.59983	Normal						
01/7/24	16:54:0	43	0.1	300	30.3	3000	3122	G	26.81897	85.62983	Normal						
01/7/24	16:54:0	43	0.1	360	20.2	3600	3787	G	26.8185	85.62894	Culvert						
01/7/24	16:54:35	43	0.1	300	30.3	3000	3122	G	26.81824	85.62805	Normal						
01/7/24	16:55:0	43	0.1	300	20.2	3000	3122	G	26.81798	85.62705	Curve						
01/7/24	16:55:10	43	0.1	280	20.2	2800	2900	G	26.81774	85.6262	Normal						
01/7/24	16:56:0	43	0.1	330	20.2	3300	3454	G	26.81807	85.62529	Normal						
01/7/24	16:56:0	43	0.1	320	20.2	3200	3343	G	26.81807	85.62529	Normal						
01/7/24	16:56:21	43	0.1	350	10.1	3500	3676	G	26.81767	85.62441	Curve						
01/7/24	16:57:31	43	0.1	310	20.2	3100	3233	G	26.817	85.62372	Normal						
01/7/24	16:58:7	43	0.1	260	20.2	2600	2679	G	26.8168	85.62279	Normal						
01/7/24	16:58:42	43	0.1	270	10.1	2700	2789	G	26.81629	85.62199	Normal						
01/7/24	16:58:42	43	0.1	240	20.2	2400	2457	G	26.81629	85.62199	Normal						
01/7/24	16:59:17	43	0.1	340	20.2	3400	3565	G	26.81634	85.62111	Normal						
01/7/24	17:0:0	43	0.1	330	20.2	3300	3454	G	26.81668	85.6202	Normal						
01/7/24	17:0:0	43	0.1	280	20.2	2800	2900	G	26.81726	85.61951	Normal						
01/7/24	17:0:28	43	0.1	330	20.2	3300	3454	G	26.81781	85.61872	Culvert						
01/7/24	17:1:0	43	0.1	330	20.2	3300	3454	G	26.81838	85.61795	Normal						
01/7/24	17:1:3	43	0.1	310	10.1	3100	3233	G	26.81889	85.61712	Normal						
01/7/24	17:1:3	43	0.1	270	10.1	2700	2789	G	26.81941	85.6163	Normal						
01/7/24	17:1:38	43	0.1	330	20.2	3300	3454	G	26.81982	85.61535	Normal						
01/7/24	17:2:0	43	0.1	340	10.1	3400	3565	G	26.82018	85.61448	Normal						
01/7/24	17:2:13	43	0.1	330	20.2	3300	3454	G	26.82056	85.6136	Normal						
01/7/24	17:2:13	43	0.1	300	20.2	3000	3122	G	26.82056	85.6136	Normal						
01/7/24	17:2:13	43	0.1	280	20.2	2800	2900	G	26.82083	85.61264	Normal						
01/7/24	17:3:0	43	0.1	240	20.2	2400	2457	G	26.82057	85.61175	Normal						
AVERAGE 3200																	

1/19/24

01/17/24

01/07/24