

~~366~~

Muzadlin Tatbandh road to
Rehri Narka to 19 (SC)
Munshi (SC)

Measurement Book

Schedule XLV-Form No. 134

at 03/06/2020
Agreement No. - 38-SBD of 20-21

Baghia-2

DIVISION

9

SUB-DIVISION

21

Bhitchha.

Mr. Om Shri Chai Construction Co. App'd

Sch. XLV-Form No. 13

Abstract of cost for 2nd year
Maintenance bill.

42

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
15.1 - Restoration of drain culvert.					
V.T.M.B.P. 6 (40) - 1/4 (1) = 43.47 m ³					
Chs. 906 = 82 / m ³ Rs. 178.88 = 00					
15.2 - Making up of Beams & Slab					
V.T.M.B.P. 7 (1) x 1/2 (2) = 3.54 m ²					
Chs. 61 = 70 / m ² Rs. 21.842 = 00					
15.3(iii) - Patch repair over P.T.S.					
V.T.M.B.P. 6 (1) x 1/4 (3) = 37.73 m ²					
Chs. 321 = 75 / m ² Rs. 121.39 = 00					
15.7(vi) - Maintenance of slab culvert &c					
V.T.M.B.P. 6 (1) x 1/4 (2) = 1 m ² .					
Chs. 23 = 21 each Rs. 3.329 = 00					
15.9 - Maintenance of 2 ft. 6 in. -					
V.T.M.B.P. 1 (4) x 1/2 (5) = 0.57 m ²					
Chs. 1077 = 81 / m ² . Rs. 636 = 00					
15.11 - maintenance of 200 mff					
K.R. 6 stone - 8					
V.T.M.B.P. 2 (4) x 1/2 (6) = 7.18 m ² .					
Chs. 702 = 29 / m ² . Rs. 829 = 00					
15.12(i) - cutting of branches off trees					
V.T.M.B.P. 6 (1) x 1/2 (7) = 2 m ²					
Chs. 109 = 74 each Rs. 219 = 00					
15.12(ii) - cutting at 5 places off					
V.T.M.B.P. 6 (1) x 1/2 (8) = 9 m ² .					
Chs. 6 = 73 each Rs. 61 = 00					

Grs. Rs. 55943 = 00

Continuation

Sch. XLV-Form No. 134

Continuation