

194/2018-19

विपरीत अंतरांतर

Schedule XLV Form No.-134
Bihar P.W.D.

पुनरांतर

DIVISION

अधिकांश

SUB-DIVISION

MEASUREMENT BOOK

विपरीत अंतरांतर

3rd Year Maintenance

Sch. XLV-Form No.134

54

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work -	Maintenance of Road from				
Mogolapur Lohor to Lakshmi Talor.					
	under (m.m.b.s.y.s.c.)				
Agency:-	Gudiga Dori				
Agreement No -	30580/2018-2019				
Date of Start -	22.10.2018				
Date of comp -					
Actual date of comp -					
• <u>Swati</u> 24.10.2022 J.E.  24/10/2022					
(1) Restoration of Raincuts.					
5 x 4.00 x 0.90 x 0.30 =	5.40m ²				
8 x 6.00 x 0.85 x 0.25 =	10.20m ²				
10 x 6.10 x 0.90 x 0.30 =	16.47m ²				
	32.07m ²				
(2) Making up of Berms/shoulder.					
4 x 3.00 x 0.90 =	10.80m ²				
8 x 6.10 x 0.85 =	40.81m ²				
10 x 9.00 x 0.90 =	81.00m ²				
9 x 6.40 x 0.80 =	46.08m ²				
	178.68m ²				
(3) Patch repair on already ex					
4 x 1.50 x 0.90 =	5.40m ²				
8 x 1.30 x 0.85 =	8.84m ²				
12 x 1.60 x 0.90 =	17.28m ²				
Continuation					31.52m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) Repair to pot holes etc. Qty. made R.M.P (54) items No.					
(5) is same Qty =					31.52 m
(5) Maintenance of c/o work.					
			2.00	No.	
(6) Maintenance of Road Signs.					
			0.14	km	
(7) Maintenance 200M 2 km stone.					
			0.16	km	
(8) cutting of branches of trees.					
			1.00	No.	
(9) cutting of shrubs Road.					
			5.00	No.	
(10) Trimming of grass & lawns.					
2 x 30.00 x $\frac{0.18+0.20}{2}$ =					11.40 m
(11) White washing on parapet.					
1.3 x 2 x 7.10 x 100 =					42.10 m
(12) Repair pot holes field.					
4 x 1.50 x 0.90 x 0.075 =					0.40 m ³
8 x 1.80 x 0.85 x 0.075 =					0.91 m ³
10 x 1.60 x 0.90 x 0.075 =					1.08 m ³
					2.39 m ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
(1) Restoration of Rainwater with diff.					
- do - do all complete job.					
Qty. vide T.M.B.P (54) = 32.07 m ²					
② H 320219/m ² → R					102682.00
(2) Maintenance of Earth & sl.					
Qty. vide T.M.B.P (54) = 178.68 m ²					
② H 50291/m ² → R					90972.00
(3) Patch repair on already.					
Qty. vide T.M.B.P (54) = 31.52 m ²					
② H 247255/m ² → R					7802.00
(4) Repair to Pot holes etc.					
Qty. vide T.M.B.P (55) = 31.52 m ²					
② H 265268/m ² → R					8374.00
(5) Maintenance of c/d work.					
Qty. vide T.M.B.P (55) = 2.00 No.					
② H 1107235/each → R					22082.00
(6) Maintenance of Road sign.					
Qty. vide T.M.B.P (55) = 0.12 km					
② H 1070225/km → R					1552.00
(7) Maintenance of 200m x 2km.					
Qty. vide T.M.B.P (55) = 0.16 km					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
①	15	4842	95/km	→ 15	79200
(8) Cutting of branches of trees.					
Qty. vide T.M.P (55) = 1.00 No.					
②	18	104248	/each	→ 18	104200
(9) Cutting of shrubs from Road.					
Qty. vide T.M.P (55) = 5.00 No.					
③	18	6242	/each	→ 18	32000
(10) Trimming of grass & weeds.					
Qty. vide T.M.P (55) = 11.40 m ²					
④	18	214	/m ²	→ 18	27200
(11) White washing on wall.					
Qty. vide T.M.P (55) = 42.00 m ²					
⑤	18	1605	/m ²	→ 18	67400
(2) Patch repair pot holes.					
Qty. vide T.M.P (55) = 2.39 m ²					
⑥	18	463	53/m ²	→ 18	111000
					As 3992700
Less 10% as per below (1)					As 399300
					As 3593400
Subt 24.10.2022 J.C. 24.10.22 AS					