

5th Year Maintenance Bill

31

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- 1046 50 Bhumiwar					
Tola 30 Age Duk.					
Agency:- Bimla Singh.					
Agg No:- 58 SBD/2018-19					
Date of start:- 11.09.2018					
Actual Date of compl:- 08.3.2019.					
Measurement					
① Restoration of rain pits					
with soil --- do ---					
Complete no.					
	3x5	0x0.9	0.324	0.50	
	4x7	0x0.8	0.3	6.720	
	2x5	0.00x0.5	0.32	1.500	
	3x6	0.00x0.8	0.90	4.320	
	5x4	0.00x0.9	0.30	5.40	
				= 21.990 m ³	
② Making up loss of material					
on shoulder to the drain do ---					
	6x3	0.00x1.05	18.900		
	5x2	0.00x1.00	11.000		
	4x2	0.50x1.125	11.250		
	5x2	0.50x0.80	10.00		
	8x6	0.00x1.05	50.400		
	5x4	0.00x1.20	24.00		
			= 125.550 m ³		

Scanned with CamScanner