

1st year maintenance

55

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
Name of work - point of roof					
from N1872 to chakir chong					
1207 190205.					
Agency - Probhat Kirod					
Agreement No - 126300/19100					
Date of work - 10.12.2019					
Actual Completion - 07.05.2022					
Receding Entry					
for restoration of soil					
work with soil					
6x	5.80	x 0.50	x 0.30	=	8.75
7x	4.60	x 0.90	x 0.30	=	8.69
6x	5.30	x 0.70	x 0.30	=	6.68
4x	6.80	x 0.90	x 0.30	=	7.34
8x	3.40	x 0.75	x 0.30	=	6.12
4x	5.50	x 0.65	x 0.30	=	4.29
9x	3.90	x 0.85	x 0.30	=	10.00
4x	5.90	x 0.95	x 0.30	=	6.73
7x	5.70	x 0.80	x 0.30	=	9.58
6x	4.30	x 1.10	x 0.30	=	8.51
Total					76.29
(2) point of roofing					
8 shingles					
2x	9x 6.40	x 0.70	=	80.64	
2x	8x 2.10	x 0.60	=	68.16	

Continuation

[illegible]

protocol used	
Graph paper -	26.29 T
Balance 390 -	82 10g
S. chips -	0.95 T
Crosted salt -	0.22 T
Balance balance note Page (24)	
	1/3 10g
Balance -	82 10g
Balance -	56 10g
	

Continuation