

2nd year maintenance

60

Sch. XIV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
name of work. Repair of roof from N.W. to Chaker Mand Khan Nagar					
agency - Probhat Kiron					
Agreement no - 120300/19.20					
Date of work - 10.12.2019					
Actual completion - 07.05.2022					
Record Entry					
(1) Restoration of roof					
cut pit for					
— 20 —					
6 x 5.80 x 1.10 x 0.30 = 11.48					
9 x 6.60 x 0.70 x 0.30 = 12.02					
12 x 3.40 x 0.65 x 0.30 = 7.96					
6 x 4.80 x 0.95 x 0.30 = 8.12					
2 x 3.70 x 0.75 x 0.30 = 5.82					
9 x 5.60 x 0.80 x 0.30 = 12.01					
6 x 5.90 x 0.85 x 0.20 = 7.92					
8 x 4.70 x 0.85 x 0.30 = 9.59					
8 x 6.05 x 1.10 x 0.30 = 15.92					
Total = 91.49					
(2) Repair of roof					
shingles etc.					
2 x 6 x 5.60 x 0.70 = 60.48					
2 x 8 x 7.30 x 0.85 = 97.28					
2 x 7 x 5.60 x 0.80 = 62.72					

Continuation

Continuation
09/24/24
28