

NH-107 रीजिस्टर ऑफ अर **M.B.No-332**
2019-2020

संकेत असा सीमानक
Schedule XLV-Form No. 134
संवत् २०१९-२०२० मध्ये न.१३४ (१३ रु.)

R.M.D. Gadhani DIVISION

अण्ण ग. गंधी SUB-DIVISION

Chandan Kumar.

Measurement Book

MMGSY (NDB) BRIDGE

प्रमाणित किया जाता है कि इस
मापी पुस्त में मशीन द्वारा अंकित
कुल-100 (एक सौ) पन्ने हैं जिस
में संजय कुमार, सहायक अभियंता
कार्य अपर प्रमंडल, बेलदौर का
निर्गत किया जाता है.


19.6.19
कार्यपालक अभियंता
प्रामीण कार्य विभाग
कार्य प्रमंडल-गोगरी
19.6.19

Sch. XLV-Form No. 134

R.W.D.-Gogri DIVISION

अपर प्रमंडल SUB-DIVISION

Measurement Book

No. 332

Name of Officer _____

2nd year maintenance

Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Construction of road from H.H. 102 House of Shaibinda Verma to Ksham. Gadd. 2. m. to k					
Agency - Chandan Kumar					
Agreement No. 01 B.B.D. of 2019.2020					
Date of start. 18.06.2019					
Date of comp. 17.06.2020					
Actual Date of comp. 18.07.2020					

① Restoration of Dolin cuts

Berms 10.4/10.11
margin etc.

$$2 \times 30.00 \times 1.00 \times 0.15 = 9.00 \text{ m}^2$$

$$2 \times 25.00 \times 1.00 \times 0.15 = 7.50 \text{ m}^2$$

$$2 \times 20.00 \times 1.00 \times 0.15 = 6.00 \text{ m}^2$$

$$2 \times 15.00 \times 1.00 \times 0.15 = 4.50 \text{ m}^2$$

$$\text{Total } 27.00 \text{ m}^2$$

② Making up Berms

shoulders stripping

Excess Soil -

$$2 \times 30.00 \times 1.00 = 60.00 \text{ m}^2$$

$$2 \times 20.00 \times 1.00 = 40.00 \text{ m}^2$$

$$2 \times 10.00 \times 1.00 = 20.00 \text{ m}^2$$

$$2 \times 15.00 \times 1.00 = 30.00 \text{ m}^2$$

$$\text{Total } 150.00 \text{ m}^2$$

ABSTRACT COST

Sch. XLV Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of berms					
Berms with soil					
moorum - do -					
Qty. vol. T.M. 11 (35)					
inv. 11 (1) 22.00 m ²					
② 380.58 / m ² = 10276 =					
② making up of Berms					
Shoulders striping					
excav soil -					
Qty. vol. T.M. 11 (35)					
inv. 11 (2)					
③ 150.00 m ²					
④ 58.37 / m ² = 8755 =					
③ patch repair of pote					
hole and priming					
open graded surface					
Qty. vol. T.M. 11 (36)					
inv. 11 (3) 14.13 m ²					
④ 231.03 / m ² = 3357 =					
④ Maintenance of					
gum and fm					
2 km do -					
Qty. vol. T.M. 11 (36)					
inv. 11 (4)					
⑤ 0.06 Km					
⑥ 1074.51 / km = 64.00					
⑦ 22452 =					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) Maintenance of Road & Gravel					
Qty of Road Material (36)					
Qty of (5)					
01 - 0.07 km					
(6) 575.12 / km ~					40.00
(6) Cutting of Branch of Tree and Shrub					
Qty of Road Material (36)					
Qty of (6.9, b, c)					
01 5 Nos @ 6.56 / m = 32.80					
01 1 No @ 106.52 / m = 106.52					
01 1.80 m @ 2.18 / m ² = 4.00					
Total 22636.00					
Less 3.00 / Below -					681.00
Net 21955.00					
01/10/23					
AB					
ced					
Material Statement					
01 R/W -					49.50 m ³
02 Stockpile -					438 m ³