

3rd Year Maintenance Bill

81

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:-					Maintenance
Road of Siwan Mairwa B.T					
Path to Syampur Village					
Haridan Tola via chimney-					
Name of Agency:-					Sritraj Kumar
Singh, Po-Blanta, Pokuwa, Distt-Siwan					
Agg No-					9/SB.D-2018-19
Date of Start-					16-11-18
Date of Complet-					15-11-19
Actual completion-					15-06-19

Item no(1)	Restoration of Roadcut				
4 X	2.10 X 1.20 X 0.30				3.02
4 X	2.25 X 1.20 X 0.30 =				3.24
6 X	5.00 X 1.50 X 0.30 =				13.50
6 X	4.50 X 1.50 X 0.30 =				12.15
6 X	3.50 X 2.00 X 0.30 =				12.60
8 X	5.00 X 1.40 X 0.30 =				16.80
4 X	6.00 X 1.00 X 0.30 =				12.96
4 X	5.00 X 2.25 X 0.30 =				13.50
					<u>Total 87.77 m³</u>
Nett Qty-					<u>87.77 M³</u>

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
① Restoration of pavement					
Qty = 27.77 m ³					
@ Rs 365 = 25/m ³					Rs 32057 = ^u
② Making up Berm/shoulder					
stripping do do					
Qty = 324 m ²					
@ Rs 54 = 16/m ²					Rs 17540 = ^u
③ Repair of Potholes					
do do					
Qty = 65.75 m ²					
@ Rs 360.30/m ²					Rs 24215 = ^u
④ Patch Repair over					
potholes Premixing					
Qty = 65.75 m ²					
same Item no - ③					
@ Rs 291 = 55/m ²					Rs 19169 = ^u
⑤ Patch Repair over Bitu					
minors surface 20 mm					
Qty = 65.75 m ²					
@ Rs 311 = 66/m ²					Rs 20491 = ^u
					Total Rs 113400 = ^u

Continuation

4th Year Maintenance Bill

87

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work:— Maintenance					
Road of Siwan pairwa B.T Road					
ke Srambur Village Harijan Tola					
via- chimaray					
Name of Agency:— Shree					
Anuj Kumar Singh					
Village-PO- Bhanu Pakhar					
Date of start — 16-11-18					
Date of complt — 15-11-19					
Date of Actua complt — 15-06-19					

① Restoration of Reinnett					
Barms with soil Mosson					
4 X	2.50	X	1.20	X	130 = 3.60
4 X	2.40	X	1.20	X	130 = 3.45
6 X	4.00	X	1.50	X	130 = 10.80
6 X	5.00	X	1.40	X	130 = 12.60
6 X	4.50	X	1.60	X	130 = 12.96
5 X	3.00	X	2.50	X	130 = 11.25
7 X	5.00	X	2.00	X	130 = 21.00
4 X	5.00	X	2.25	X	130 = 13.50
10 X	3.00	X	1.00	X	130 = 9.00
Total					98.16 m ³

Continuation

Particulars	Details of actual measurement				Contents of area.
	No.	L.	B.	D.	
<u>Abstract of Cost</u>					
① Restoration of Reinnett					
Qty —	98.16	m ³			
@ Rs 365 = 25/m ³					Rs 35853
② Making up Berm/shoulder					
strippy do do					
Qty —	401.00	m ²			
@ Rs 54 = 16/m ²					Rs 21718 =
③ Repair of Pot Holes					
do — do — con					
Qty —	84.75	m ²			
@ Rs 368 = 30/m ²					Rs 31213 =
④ Patch Repair over					
Pot Holes do do					
Qty —	84.75	m ²			
@ Rs 291 = 55/m ²					Rs 24709 =
⑤ Patch Repair over Bitu					
minous surface Pav					
Qty —	84.75	m ²			
@ Rs 311 = 66/m ²					Rs 26413 =
Total					Rs 139906 =

