

(153)

M. 14. 61. 5. 8 (S. C.) MB No-188

Schedule XLV-Form No. 134

BIRPUR TOLA G. N. BAWDHA TD

DIVISION

MAHADALIT TOLA BIDPUR-41AB12AN

SUB-DIVISION

TOLA

Anga Inkra Pvt Ltd.

Measurement Book

પ્રમાણિતકિયા જાણા છે કિ રૂ ૫
 માપી પ્રાંત મશીન દાય આંકિ
 કુલ - 100 (પચાસી પ-ને છે) જા
 ૪૦ જા મિલિતેય કુમાલ મદાય
 અભિયંત્ર અવલ કાર્ય પ્રમાણત
 પલત્રા કો નિર્ણિત કિયા જાણા છે


 23.02.17

Executive Engineer
 S.W.D. Works Dept.
 Gandhinagar

Jamnagar
 23.02.17

Sch. XLV—Form No. 134

_____ DIVISION

_____ SUB-DIVISION

Measurement Book

No.

5th year maintenance

name of work: - maintenance of road from Warbur to a horizon tolg

Name of Agency:	Onge Dohg
Int. Ltd	

Assg no: -21SBD/16-17

Date of Commencement:				
			10-12-2016	

Deuxes completion:

			10-03-2019	
--	--	--	------------	--

Date of entry: 10-4-24

Record measurement

Continuation

Abstract of 0001

① Restoration of rain
cuts / Berme with soil
micrometric — au
cent — 006

Obvise in this ring

P.no (83) item no ①

= 292.90 m³

@ 321.51/m³ — 94170 = ~

② making up of berme
/ shoulder stripping of
excess soil — au carbon

Obvise in this ring

P.no (84) item no ②

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
dry - 814 m ²					
② 49.87/m ² ——— n 39943 =					
③ Patch repair over					
pot holes with 20 mm					
premix carpet - 100 mm					
at vide in this m. 3					
P. no ⑧④ item no ③					
= 104.96 m ²					
④ 269.49/m ² ——— n 28286 =					
④ Patch repair over					
bituminous surface					
with 20 mm premix carpet					
— — — — —					

at vide in this m. 3					
P. no ⑧④ item no ④					
= 104.96 m ²					
⑤ 269.49/m ² ——— n 28286 =					
⑤ Maintenance of C.O.					
work					
at vide in this m. 2 P. no					
⑧⑤ item no ⑤ = 1 no					
⑥ 904.35/each ——— n 904 =					
⑥ White washing at					
boundary walls — — — — —					
Cont. - 200					
at vide in this m. 3					
P. no ⑧⑤ item no ⑥					
= 20.16 m ² @ 29.34/m ² ——— n 591 =					

Continuation n 192180 =

↓ c o

[illegible]