

1st Year Maintenance

48

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
Name of work - Maintenance of road from Masaula Chainpur Path Hasanpur to Banjraha Tak under NABARD						
Agency - Jftekhar Alam						
At - Kushmahwa, E. Champaran						
Agreement No - 88 SBD/2019-20						
Date of start - 25/04/2018						
Actual date of Completion - 22/04/2019						
Maintenance of work done has been done by Agency and Voucher of work done has been produced as taken for the club 100th						

Abstract of work

Sch. XLV-Form No. 134

59

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of Raincut					
Q-VIMB/50(1) = 52.12 H					
P 51(1) = 13.84 H					
				65.96 H	
e h 343 = 12/H					22632 = 0
(2) Maintenance of earthen shoulder					
Q-VIMB/48(1) = 115.92 H					
P 49(2) = 250.85 H					
				366.77 H	
e h 50 = 60/H					1855920
(3) Maintenance of bitumen surface road					
Q-VIMB/51(1) = 30.55 H					
e h 294.65/H					9002 = 0
(4) Maintenance of slab culvert					
Q-VIMB/50(1) = 4 Nos					
e h 2227.52/each h					8910 = 0
(5) Maintenance of road sign					
Q-VIMB/51(1) = 1.31 km					
e h 1038.77/km h					1361 = 0
(6) Maintenance of 200 m and km stone					
Q-VIMB/51(1) = 1.31 km					
e h 557 = 45/km h					730 = 0
(7) cutting of branches of trees					

Continuation

61194 = 0

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Q-VMDP 49(3) = 3 Nos					230=0
ch. 100=91/each h.					303=0
(8) Cutting of shrubs					
Q-VMDP 49(3) = 14 Nos					
ch. 6.19/each h.					87=00
					61,584=0
Less 2.07 f. below -					1275=00
					60,309=00
<u>Arba</u>					
30.05.20					
S.E. RANA Abaka					2015/1110
G.P. Armed					500
23/3/23					0005=0
EZ					