

Sch. XLV—Form No. 134					Contents of area	
Particulars	Details of actual measurement					
	No.	L.	B.	D.		
4th year maintenance						
Name of work - maint of road from parari to Manguraha parari						
Agency-Prudesh shukla						
Agg.no - 10SPD/2017-18						
D/S - 18/1/2018						
A/D/C- 19/10/2019						

## ① Restoration of rain cuts -

$$25 \times 2.25 \times 1.6 \times 0.30 = 27.00 m^3$$

$$28 \times 1.85 \times 1.45 \times 0.80 = 22.53 \text{ m}^3$$

$$36 \times 2 = 10x \quad 1.75 \times 0.30 = 39 \quad 0.69 m^3$$

$$= 89 : 22 m^3$$

② Minitr of earther shoulder with

soil

$$27.27 \times 8.50 \times 1.10 = 252.45$$

$$31 \times 7.25 \times 1.10 = 247.23$$

$$= 499.68 \text{ m}^2$$

### ③ Maint. of H.P. culvert

$$1 \times 2 \text{ nos} = 2 \text{ nos}$$

④ Maint of RCC summit

$$1 \times 1 \text{ nos} = 1 \text{ nos}$$

### Continuation

State of N.Y.—Form No. 134

Set Sch XLV—Form No. 134		Details of actual measurement				Contents of area
No.	L.	B.	D.			
⑦ Cutting of branches of tree						
Qty vide p.m. (55) of TMB						
7 nos @ 84.78						= 593 = 00
⑧ Cutting of shrubs						
Qty vide p.m. (55) of TMB						
14 nos @ 5.20						= 72.8 = 00
⑨ Trimming of grass and weeds						
Qty vide p.m. (55) of TMB,						
1180.41 m <sup>2</sup> @ 1.73						= 2042 = 00
⑩ Lime washing on parapet walls						
Qty vide p.m. (55) of TMB						
4160 m <sup>2</sup> @ 14.16						= 589 = 00
						= 6104 = 00
Less 10% Below						= 6104 = 00
<u>Signed</u>						= 54837 = 00
18/10/23						
J. E. K.						
<del>Mr. Radhakrishnan</del>						
<del>18/10/23</del>						

### ***Continuation***