

15+ year maintenance

51

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Can Maint. of Road					
from Mushra Jula Bahad					
Panchu mlyo Ke Ghor do					
Bithelpur Sadin PM 627					
Sadok Jala					
Agency - Rongma Kuna					
Agreement no 38/536/2021/22					
Date of Start - 21.07.21					
Date of actual comp. 30.06.23					

Work Done

1. Restoration of water cut
do do all comp ok

2x23x	$\frac{1.1+0.8}{2} \times 0.3 = 13.11$			
3x15x	$\frac{0.7+0.5}{2} \times 0.32 = 8.10$			
5x16x	$\frac{1+0.7}{2} \times 0.3 = 20.40$			
6x21x	$\frac{1.1+0.8}{2} \times 0.32 = 35.91$			
2x20x	$\frac{0.8+0.5}{2} \times 0.3 = 7.26$			
4x23x	$\frac{1+0.7}{2} \times 0.3 = 23.46$			
3x24x	$\frac{1.1+0.8}{2} \times 0.3 = 20.52$			
				129.30 m ³

2. Maint. of earthen

Shoulder do do 24

Comp ok

6x14x	$\frac{1.1+0.8}{2} = 79.8$			
5x18x	$\frac{1+0.8}{2} = 81.0$			
6x23x	$\frac{0.9+0.7}{2} = 110.4$			

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) Main ^t of culvert d					
do all comp 1.5					
Qty rd. m ³ P 52: 2.10					
@ R 2373-47/each				R 474720	
5) Main ^t of 200 m and					
km stone do-d					
all comp 1.5					
Qty rd. m ³ P 53: 3-59 km					
@ R 711.43/km				R 217620	
				R 11100020	
Add G 07 12 x				R 1332020	
Add LS 14.				R 111020	
				R 12543020	
less 13% on agreement				R 1630620	
				R 10912420	
				Ala	
				28.16.24	
				ME	
				28/6/2024	
				A.E	