

5<sup>th</sup> yr. maintenance  
bill

55

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of waste chakrums					
bidin P.A Cooperative					
Ramle se utas rangra					
chowk se Abdulpur					
mukhya many prabhu toll					
Agency - muresh kumar					
Agg. no. - 24/SBD/2018-19					
Actual date of comp - 24.5.19					
5 <sup>th</sup> yr. maintenance period					
- 25.5.23 to 24.5.24					

① Restoration of rain

cuts

$$2 \times 2 \times 30.0 \times 0.90 \times 0.45 = 48.60$$

$$2 \times 3 \times 17.75 \times 1.0 \times 0.3 = 31.95$$

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
of CD waste					
19.88 m <sup>2</sup> vide Form No. (5)					
@ 15 = 65/m <sup>2</sup> =					311 =
					<u>136638 =</u>
Less 10% as per aged -					13664 =
					<u>122974 =</u>
<del>@ Gupta 26.5.21</del>					
<del>@ Gupta 26.5.21 AE</del>					
<del>us Samir 05/01/21</del>					