

9th year maintenance

35

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: 622 to Hatha					
Crack 70/9					
2. Agency: Manoj Kumar					
3. Agreement no. 61/330/2019-20					
4. Actual date of completion: 03.07.2020					
— measurement as below —					
① Restoration of drain with					
with 601-cum					
1x 30.0 x 0.60 x 0.30 =					5.40
1x 30.0 x 0.52 x 0.30 =					4.68
1x 20.50 x 0.42 x 0.28 =					2.410
1x 18.90 x 0.40 x 0.28 =					2.12
2x 30.0 x 0.35 x 0.30 =					6.30
1x 30.0 x 0.40 x 0.30 =					3.60
3x 30.0 x 0.42 x 0.30 =					11.34
1x 18.90 x 0.40 x 0.28 =					2.12
					Qty = 37.97m ³
					Say Qty = 37.75m ³
② maintenance of drain					
shoulder-cum					
1x 30.0 x 0.60 =					18.00
1x 30.0 x 0.57 =					15.60
2x 30.0 x 0.45 =					27.00
1x 30.0 x 0.38 =					11.40
1x 30.0 x 0.48 =					14.40
1x 30.0 x 0.48 =					14.40
Continuation					Qty = 100.80m ²

P. 710.

Continuation