

5 year maintenance

59

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: Bandra Bandra Panchayat (Bandra Panchayat (Bandra Panchayat)) Bandra Choudhary 2019					
2. Agency: Madhu Devi					
3. Agreement No: 55 SBD/2018-19					
4. Actual dt. of completion: 08.07.2019					
measurement as below					
① Rectification of drain cuts with 80/1 super					
1x 30.00 x 0.60 x 0.30 =					5.40
1x 30.00 x 0.52 x 0.30 =					4.68
1x 30.00 x 0.52 x 0.30 =					4.68
5x 30.00 x 0.40 x 0.30 =					18.00
6x 30.00 x 0.45 x 0.30 =					24.30
					Qty = 57.06 m ³
					Qty = 56.50 m ³
② maintenance of earthen shoulder - 12					
1x 30.00 x 0.60 =					18.00
5x 30.00 x 0.52 =					78.00
1x 20.50 x 0.50 =					10.25
1x 18.60 x 0.48 =					8.928
6x 30.00 x 0.50 =					90.00
6x 30.00 x 0.50 =					90.00
2x 13.00 x 0.50 =					13.00
2x 13.60 x 0.50 =					13.60
1x 1.50 x 0.20 =					0.30

Qty = 314.628 m³
Qty = 313.88 m³

P. 120

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				BF B	71290 = 0.0
⑥ maintenance of lab					
type culvert - E & W					
Qty = 4.0 nos vide					
				TM B Page (67)	
⑦ L 2287 = 21/each - R					9199 = w
⑦ maintenance of stream					
2 km stone - E & W					
Qty = 1.02 KM vide					
				TM B P - (67)	
⑧ L 675 = 29/KM - R					689 = w
					R 81078 = w
Less 10.07.2014					81085
Ram C					R 72970 = w
06-07-2014				cut	
J-E				6/7/2014	
				at	
material statement					
① earth					10358 m ³
② Bitumen 90					0.323 m ³
③ Stone chips					4.359 m ³
Ram C					
06-07-2014				cut	
J-E				6/7/2014	
				at	