

2nd year maintenance

30

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road: - M41a Pakari					
hard path to Pakari Karmi					
to la.					
Agency: - Keshav Kumar					
Agreement: - 515AD/2018-19					
Actual Date of Comp: - 14.03.2019					
Detailed measurement					
① Restoration of					
loam cut.					
4x3.20x0.850x0.20023.16m ³					
8x2.00x0.600x0.3004.20m ³					
4x2.90x0.750x0.20021.60m ³					
13x3.10x0.800x0.20029.67m ³					
9x3.30x0.580x0.2004.62m ³					
					28.86m ³
					Unit 864 - 28.81m ³
② Maintenance of					
earthen shoulders.					
2x11.0Mx0.50022.00m ²					
2x15.0Mx0.57027.10m ²					
3x29.0Mx0.65025.55m ²					
3x23.0Mx0.55027.95m ²					
4x25.0Mx0.60026.00m ²					
					188.60m ²
					Unit 864 - 188.85m ²

