

2nd year maintenance

22

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: mmbly s, ho					
Dardha path se to Harpur					
Fatah Toh					
2. Agency: madhu Devi					
3. Agreement No: 38/530/2019-20					
4. Actual date of completion: 18.07.2022					
measurement as below					
① Restoration of drain cuts					
1 with 1801 cut E					
1x 30.00 x 0.60 x 0.30 = 5.40					
1x 30.00 x 0.70 x 0.30 = 6.30					
2x 30.00 x 0.65 x 0.30 = 11.70					
1x 30.00 x 0.80 x 0.30 = 7.20					
1x 20 x 0.65 x 0.30 = 3.90					
1x 30 x 0.90 x 0.30 = 8.10					
1x 30.00 x 0.85 x 0.30 = 7.65					
1x 20.50 x 0.80 x 0.30 = 4.92					
1x 18.50 x 0.85 x 0.30 = 4.717					
1x 20.60 x 0.90 x 0.30 = 5.562					
2x 30.00 x 0.85 x 0.30 = 15.30					
1x 20.60 x 0.70 x 0.30 = 4.326					
1x 30.00 x 0.65 x 0.30 = 5.85					
1x 20.50 x 0.70 x 0.30 = 4.305					
1x 30.00 x 0.65 x 0.30 = 5.85					
1x 5.0 x 0.60 x 0.30 = 0.90					
1x 5.0 x 0.60 x 0.30 = 0.90					

1x 2.50 Continuation 6.50 x 0.30 = 0.375

948 = 103.255

948 = 102.914

⑦	mark variance of		
8	room & km stone		
—	clw E12		
Qty =	2-70x km wide		
	Tom B page (22)		
⑧	135 = 27 / km	— B	1985 = 0
	(100 / B		11310 = 0

col	row
12/1/2001	AB

Material statement	
⑩ earth	188.67m
⑪ Return sand	0.167m
⑫ Stone chips	2.19m

Continuation

12/20/24