

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work: -	Partsona	Dhobi	Tola	Samudayak	
Shaninto	Baidyanathpur.				
Agency: -	Ranjit Thakur				
	Partsona (Muz)				
App. No: -	60 SED	2017-18			
Date of start: -	09.09.2017				
Date of Completion: -	08.09.2018				
Actual Date of Completion: -	15.06.2018				
Date of Measurement: -	16.06.2020				
	Work done				
① Restoration of rain cuts with soil					
- do-do - all complete job.					
	$2 \times 8 \times 30.0 \text{ M} \times \frac{0.40 + 0.30}{2} \text{ M} \times 0.45 \text{ M} = 75.60 \text{ M}^3$				
	$2 \times 4 \times 30.0 \text{ M} \times \frac{0.45 + 0.35}{2} \text{ M} \times 0.50 \text{ M} = 48.00 \text{ M}^3$				
	$2 \times 5 \times 30.0 \text{ M} \times \frac{0.40 + 0.30}{2} \text{ M} \times 0.26 \text{ M} = 27.30 \text{ M}^3$				
					150.90 M ³
② Maintenance of earthen Shoulders					
- do-do - all complete job					
	$2 \times 9 \times 30.0 \text{ M} \times \frac{0.55 + 0.60}{2} \text{ M} = 297.00 \text{ M}^2$				
	$2 \times 6 \times 30.0 \text{ M} \times \frac{0.55 + 0.65}{2} \text{ M} = 216.00 \text{ M}^2$				
	$2 \times 9 \times 30.0 \text{ M} \times \frac{0.55 + 0.66}{2} \text{ M} = 326.70 \text{ M}^2$				
					839.70 M ²
③ Maintenance of slop Culverts					
- do-do - all complete job					
	5 Nos				

Continuation

Continuation