

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

3rd year maintenance  
from - 11-06-2023 to 10-06-2026

Name of work - Maintenance of

Road from Ramgurbux to Soz

Agency - Satender Kumar Rai

Agreement no. - 521530, 2020-21

Date of start - 15/09/20

Actual date of completion - 10/06/21

Date of measurement - 10/6/26

1 Restoration of draincut  
with soil, Mortar &  
gravel

$$1 \times 18.2 \times 2 \times 0.9 \times 0.30 = 9.96$$

$$1 \times 9.5 \times 2 \times 1.05 \times 0.30 = 5.985$$

$$15.96$$

$$15.915$$

$$\text{for } 14.88 \text{ m}^3$$

2 Maintenance of  
earthen shoulder

$$1 \times 30 \times 2 \times 0.90 = 54.0$$

$$1 \times 20 \times 0.85 = 17.0$$

$$1.0 \text{ m}^2$$

$$\text{for } 70.88 \text{ m}^2$$

3 Maintenance of  
road surface

9811.43

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5 Main tenance 52					

Soil, Dingeo  
Width item No (3) PN. 29  
 $QH = 0.03 \text{ km}$   
 $\therefore 1070 = 82 \text{ km} - 32 = 33$

5 Main tenance 58  
 10 mm stone @ 15.m  
 Stone  
 Width item No (4) PN. 30  
 $QH = 0.04 \text{ km}$   
 $\therefore 688 = 26 \text{ km} - 85 = 13$

Say: 9869 = 0  
 Add 12). GST + 17. 9868 = 88  
 GST 1184 - 1282 = 85  
 Less 0.57 / action 50 = 33  
 L. Red. 99 - 1151881  
 5.51 below 54381  
 1113 - 0.563 = 23  
 10755 - 0.563 = 23  
 49325 = 12  
 See 627325 = 10  
 10955 = 0  
 11159 = 0  
 Total 1151 = 86  
 Less 5.51 below 614 = 67  
 10537 = 66  
 10537 = 66  
 6.m. + 10537 = 66  
 10537 = 66  
 My sum 10614  
 Continuation 10614  
 5