

Sch. XLV-Form No. 134

Sch. XLV-Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
Name of work:- Construction of road with maintenance work from Anita PMGSY Road to Dumariga.					
Name of agency:- Sri Bhagwan Jha.					
Agreement No.:- 17 SBD/2018-19. (MMGSY-SC)					
Date of report:- 09.06.2018.					
Date of Completion:- 08.03.2019.					
Actual date of Completion:- 07.03.2019.					
Date of entry:- 30.06.2022					
① Restoration of pavement					
Ditch soil - dado					
Ref	1x	20.00	0.90	0.60	10.80 m ³
	2x	15.00	0.60	0.60	32.40
	6x	20.00	0.80	0.45	43.20
	3x	12.00	0.90	0.50	16.20
	4x	15.00	0.80	0.50	24.00
					126.60 m ³
② Making up of Barrow/					
Shoulder, stripping excess					
soil from the shoulder					
Surfaces to achieve level, dado					
Ref	2x14x	30.00	2.80		672.00 m ²
	2x1x	19.00	0.80		30.40
					702.40 m ²
③ Repair of pot holes					
Ditch 75mm BM.					
Hand					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3) <u>continued.</u>					
15x	2.50	0.90	0.075		2.53 m ³
7x	3.00	0.40	0.075		1.42 "
6x	4.00	1.00	0.075		1.80 "
2x	3.50	1.20	0.075		0.63 "
					<u>6.38 m³</u>
(4) Patch repair over pot holes & to surface dressing					
15x	2.50	0.90			33.75 m ²
7x	3.00	0.90			18.90 "
6x	4.00	1.00			24.00 "
2x	3.50	1.20			8.40 "
					<u>85.05 m²</u>
(5) Patch repair over determined surface.					
2x	5.00	2.00			20.00 m ²
2x	4.80	1.80			25.92 "
2x	6.00	2.50			30.00 "
1x	6.10	1.50			9.15 "
					<u>85.07 m²</u>
(6) Cutting of branches of trees & shrubs					0/100
(7) Cutting of shrubs from roadway					13 Nos
(8) Trimming of grass & weeds					
2x	30.00	0.50			30.00 m ²
2x	1.00	0.50			1.00 "
					<u>31.00 m²</u>

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
①	Restoration of rain water detn. soil d. d				
	V.P.	$\frac{31}{1}$	126.60.		
		Unit to 126.5/m ³			
	② RS 345 = 59/m ³				RS 43,721 = 00.
②	Making up of barney shoulders d. d				
	V.P.	$\frac{31}{2}$	702.40 m ²		
		②	RS. 50 = 96/m ²		RS. 35,794 = 00
③	Repair of pot holes				
	V.P.	$\frac{32}{3}$	8.38 m ²		
	② RS. 9862.52/m ³				RS 62,923 = 00
④	Patch repair of pot holes				
	V.P.	$\frac{32}{4}$	85.05 m ²		
	② RS. 108 = 36/m ²				RS 9,216 = 00
⑤	Patch repair over bituminous				
	V.P.	$\frac{32}{5}$	85.07 m ²		
	② RS. 97 = 63/m ²				RS 8305 = 00.
⑥	Cutting of branches from				
	V.P.	$\frac{32}{6}$	0 Nos.		
	② RS. 101 = 64 each				RS 0 = 00.
⑦	Cutting of shrubs from road way				
	V.P.	$\frac{32}{7}$	13 Nos.		
	② RS. 6 = 24 each				
					RS. 81 = 00
					C.O. RS 60,040 = 00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B.T.	Rs. 1,60,040=00
(7) Trimming / grass					
Weeds.					
V.P.	32 7			31.00 m ²	
@ Rs. 2-08/m ²					Rs. 64-00
					Rs. 1,60,104-00
less 10.00 % as per agreement					H Rs. 16,010-00
					Rs. 1,44,094-00
By <u>Behari</u> 30.06.2022				<u>Singhal -</u> 04/12/2022	
					Asl

<u>Material statement</u>		
①	Cement	200.24 m ³
②	stone aggregates 13.63 m ³	13.63 m³ 13.63 m ³ (2.27 m ³)
③	Coarse Sand.	1.02 m ³
④	Emulsion SS-1	76.56 Kg
⑤	" RS-1	67.96 Kg
⑥	Bitumen.	855.04 Kg