

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th year/maest					
Name of work, Hill Safety					
Porandla road to Madan					
Agency, Sailesh Fumary					
Agreement no SBT 15/2018					
Actual dt of completion					2.3.19
(1) Restoration of					
drain					
3 NO x 1.5m x 7.5 x .30					2.02m ³
4 NO x 1.25 x 1.20 x .30					1.8m ³
5 NO x 1.45m x 1.25 x .30m					2.71m ³
6 NO x 1.45m x 1.5 x .30					5.19m ³
7 NO x 1.75m x 1.25 x .30m					5.35m ³
8 NO x 2.25m x 1.05 x .30m					6.61m ³
7 NO x 2.5m x 1.00 x .30					5.25m ³
8 NO x 1.25 x 1.50 x .30					2.81m ³
9 NO x 1.95m x 1.70 x .30					2.89m ³
8 NO x 2.25 x 1.20 x .30					3.93m ³
9 NO x 1.95m x 1.75 x .30					3.97m ³
5 NO x 2.5m x 1.00 x .30					3.75m ³
6 NO x 3.5m x 1.00 x .30					6.3m ³
5 NO x 1.75 x 1.75 x .30					1.96m ³
4 NO x 1.95 x 1.85 x .30					1.98m ³
5 NO x 3.01 x 1.20 x .30					5.4m ³
Total					65.97m ³

Continuation

5.9.23
JE

05/09/23
AF

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8) maintenance slab culver					
1 NO @ 4 TMM P-82					
1 NO @ 2287.21/NO					= 2287
(7) Triangular of road					
6 m @ 4 TMM P-82					
6 m @ 2.14/m ²					= 13 m
Total					73372 =
Less 0.05% below 37 =					
Total					73335 =
10.6.24 SK					
10/06/24 AR					