

कार्यका नाम - रैपूरा रसूलपुर पंच से कुम्भी टोला तहसील मरवाह तहसील  
पंच निर्वाह कार्य

MANO-488

MMJSY(SC)

Schedule XLV-Form No. 134

Agreement No-26/23-D 2-2019

DIVISION

अमनौर

SUB-DIVISION

Reeta Singh

MEASUREMENT BOOK



# 4th Year Maintenance Bill

38

Sch. XLV—Form No. 134

| Particulars                        | Details of actual measurement          |       |       |       | Contents of area      |  |  |  |  |
|------------------------------------|----------------------------------------|-------|-------|-------|-----------------------|--|--|--|--|
|                                    | No.                                    | L.    | B.    | D.    |                       |  |  |  |  |
| Name of Road:-                     | Maint <sup>n</sup> of Road from Repura |       |       |       |                       |  |  |  |  |
|                                    | Rasulpur Path se Kurmi to Takhat       |       |       |       |                       |  |  |  |  |
|                                    | Tarwar Tak                             |       |       |       |                       |  |  |  |  |
| Agency:-                           | Smt. Reeta Singh                       |       |       |       |                       |  |  |  |  |
| Agreement No:-                     | 26/mmmjy/SBD/2018-19                   |       |       |       |                       |  |  |  |  |
| Date of Commence:-                 | 20.02.2019                             |       |       |       |                       |  |  |  |  |
| Date of Actual Completion:-        | 14.05.2019                             |       |       |       |                       |  |  |  |  |
| Due Date:-                         | 15.05.22 to 14.05.2023                 |       |       |       |                       |  |  |  |  |
| Date of entry:-                    | 10.06.2023                             |       |       |       |                       |  |  |  |  |
| 1. Restoration of Rain Cut / Berms |                                        |       |       |       |                       |  |  |  |  |
| —do—do—all complete job.           |                                        |       |       |       |                       |  |  |  |  |
|                                    | 16x                                    | 2.90x | 1.20x | 0.300 | 16.70 m <sup>3</sup>  |  |  |  |  |
|                                    | 15x                                    | 3.10x | 1.15x | 0.300 | 16.04 m <sup>3</sup>  |  |  |  |  |
|                                    | 14x                                    | 3.25x | 1.10x | 0.300 | 15.02 m <sup>3</sup>  |  |  |  |  |
|                                    | 18x                                    | 3.50x | 1.00x | 0.300 | 18.90 m <sup>3</sup>  |  |  |  |  |
|                                    |                                        |       |       |       | 66.66 m <sup>3</sup>  |  |  |  |  |
| 2. Making up at Berms / shoulder   |                                        |       |       |       |                       |  |  |  |  |
| —do—do—all complete job.           |                                        |       |       |       |                       |  |  |  |  |
|                                    | 20x                                    | 4.00x | 1.10  |       | 40.00 m <sup>2</sup>  |  |  |  |  |
|                                    | 16x                                    | 4.50x | 1.05  |       | 75.60 m <sup>2</sup>  |  |  |  |  |
|                                    | 4x                                     | 4.85x | 1.00  |       | 19.40 m <sup>2</sup>  |  |  |  |  |
|                                    |                                        |       |       |       | 135.00 m <sup>2</sup> |  |  |  |  |
| 3. Repair of Pot holes with WBM    |                                        |       |       |       |                       |  |  |  |  |
| Gr. 3 —do—do—all complete job      |                                        |       |       |       |                       |  |  |  |  |
|                                    |                                        |       | P.T.O |       |                       |  |  |  |  |

Continuation

# Abstract of Cost 4th Year maint<sup>n</sup> Bill

41


Sch. XLV—Form No. 134

| Particulars                                   | Details of actual measurement |    |                       |    | Contents of area |
|-----------------------------------------------|-------------------------------|----|-----------------------|----|------------------|
|                                               | No.                           | L. | B.                    | D. |                  |
| 1/ Restoration at Raincuts/Berms              |                               |    |                       |    |                  |
| —do—do—all complete job                       |                               |    |                       |    |                  |
| P-38,                                         | 66.66 m <sup>2</sup>          | @  | 365.25/m <sup>2</sup> | =  | 24,348.00        |
| 2/ Making up at Berms/shoulder                |                               |    |                       |    |                  |
| —do—do—all complete job                       |                               |    |                       |    |                  |
| P-38,                                         | 135.00 m <sup>2</sup>         | @  | 54.16/m <sup>2</sup>  | =  | 7312.00          |
| 3/ Repair at pot holes with W.B.M.            |                               |    |                       |    |                  |
| —do—do—all complete job                       |                               |    |                       |    |                  |
| P-38, 39,                                     | 28.13 m <sup>2</sup>          | @  | 378.85/m <sup>2</sup> | =  | 10,657.00        |
| 4/ <sup>Patch</sup> Repair at pot holes 20 mm |                               |    |                       |    |                  |
| —do—do—all complete job                       |                               |    |                       |    |                  |
| P-39 -                                        | 28.13 m <sup>2</sup>          | @  | 306.74/m <sup>2</sup> | =  | 8629.00          |
| 5/ Patch repair over B.T Surface              |                               |    |                       |    |                  |
| —do—do—all complete job                       |                               |    |                       |    |                  |
| P-39,                                         | 28.05 m <sup>2</sup>          | @  | 323.63/m <sup>2</sup> | =  | 9078.00          |
| 6/ Maintenance of C.P. work (H.P. Culvert)    |                               |    |                       |    |                  |
| —do—do—all complete job                       |                               |    |                       |    |                  |
| P-39 -                                        | 02 Nos                        | @  | 1131.64 each          | =  | 2263.00          |
| 7/ Maintenance of Road Signs.                 |                               |    |                       |    |                  |
| —do—do—all complete job                       |                               |    |                       |    |                  |
| P-39,                                         | 0.120 km                      | @  | 1087.62/km            | =  | 131.00           |

Continuation 0 Rs 62418.00



## Sch. XLV—Form No. 134

| Particulars                                                                         | Details of actual measurement |    |    |                                | Contents of area |
|-------------------------------------------------------------------------------------|-------------------------------|----|----|--------------------------------|------------------|
|                                                                                     | No.                           | L. | B. | D.                             |                  |
|                                                                                     |                               |    |    | B.F. $\beta$ 62,418.00         |                  |
| 8/10 Maint of 200m $\times$ 2km Stone                                               |                               |    |    |                                |                  |
| —do—do— all complete job                                                            |                               |    |    |                                |                  |
| P-39,                                                                               | 0.150 km                      |    |    | @ $\beta$ 654.33/km            | $\beta$ 98.00    |
| 9/11(i) Cutting of branches of trees                                                |                               |    |    |                                |                  |
| —do—do— all complete job                                                            |                               |    |    |                                |                  |
| P-39,                                                                               | 01 No                         |    |    | @ $\beta$ 107.98 each          | $\beta$ 107.00   |
| 10/11(ii) Cutting of shrubs from Road                                               |                               |    |    |                                |                  |
| way —do—do— all complete job                                                        |                               |    |    |                                |                  |
| P-40,                                                                               | 03 Nos                        |    |    | @ $\beta$ 6.60 each            | $\beta$ 20.00    |
| 11/11(iii) Trimming of grass & weeds                                                |                               |    |    |                                |                  |
| —do—do— all complete job                                                            |                               |    |    |                                |                  |
| P-40,                                                                               | 8.00 m <sup>2</sup>           |    |    | @ $\beta$ 2.20/m <sup>2</sup>  | $\beta$ 18.00    |
| 12/12 White washing of Parapet walls                                                |                               |    |    |                                |                  |
| —do—do— all complete job                                                            |                               |    |    |                                |                  |
| P-40,                                                                               | 41.28 m <sup>2</sup>          |    |    | @ $\beta$ 16.48/m <sup>2</sup> | $\beta$ 680.00   |
|                                                                                     |                               |    |    | $\beta$ 63,341.00              |                  |
| Less 10% below Rate                                                                 |                               |    |    | @ $\beta$ 6334.00              |                  |
|                                                                                     |                               |    |    | $\beta$ 57,007.00              |                  |
|  |                               |    |    |                                |                  |

# 5th Year Maintenance Bill

43

Sch. XLV—Form No. 134

| Particulars                          | Details of actual measurement         |       |       |        | Contents of area     |  |  |  |  |
|--------------------------------------|---------------------------------------|-------|-------|--------|----------------------|--|--|--|--|
|                                      | No.                                   | L.    | B.    | D.     |                      |  |  |  |  |
| Name of Road:                        | Maint <sup>n</sup> of Road from Repym |       |       |        |                      |  |  |  |  |
|                                      | - Rasulpur Path se karmi-tola         |       |       |        |                      |  |  |  |  |
|                                      | Takhath Tarwar-tals.                  |       |       |        |                      |  |  |  |  |
| Agency:                              | Smt Reeta Singh                       |       |       |        |                      |  |  |  |  |
| Agreement No-                        | 26/MM/MSY/3BD/2018-19                 |       |       |        |                      |  |  |  |  |
| Date of Commance -                   | 20.02.2019                            |       |       |        |                      |  |  |  |  |
| Date of Actual completion -          | 14.05.2019                            |       |       |        |                      |  |  |  |  |
| Due date:                            | 15.05.2023 to 14.05.2024              |       |       |        |                      |  |  |  |  |
| Date of entry:                       | -                                     |       |       |        |                      |  |  |  |  |
| 1. Restoration of Raincuts with      |                                       |       |       |        |                      |  |  |  |  |
| soil - do - do - all complete job    |                                       |       |       |        |                      |  |  |  |  |
|                                      | 18x                                   | 3.50x | 1.00x | 0.300: | 18.90m <sup>3</sup>  |  |  |  |  |
|                                      | 14x                                   | 3.25x | 1.10x | 0.300: | 15.02m <sup>3</sup>  |  |  |  |  |
|                                      | 15x                                   | 3.10x | 1.15x | 0.300: | 16.04m <sup>3</sup>  |  |  |  |  |
|                                      | 16x                                   | 2.90x | 1.20x | 0.300: | 16.70m <sup>3</sup>  |  |  |  |  |
|                                      | 14x                                   | 2.00x | 1.00x | 0.300: | 8.40m <sup>3</sup>   |  |  |  |  |
|                                      |                                       |       |       |        | 75.06m <sup>3</sup>  |  |  |  |  |
| 2. Marking up of Berms/shoulder with |                                       |       |       |        |                      |  |  |  |  |
| soil - do - do - all complete job    |                                       |       |       |        |                      |  |  |  |  |
|                                      | 5x                                    | 3.00x | 1.05  | :      | 15.75m <sup>2</sup>  |  |  |  |  |
|                                      | 4x                                    | 4.85x | 1.05  | :      | 20.37m <sup>2</sup>  |  |  |  |  |
|                                      | 10x                                   | 4.00x | 1.00  | :      | 40.00m <sup>2</sup>  |  |  |  |  |
|                                      | 16x                                   | 4.50x | 1.05  | :      | 75.60m <sup>2</sup>  |  |  |  |  |
|                                      |                                       |       |       |        | 151.72m <sup>2</sup> |  |  |  |  |
|                                      |                                       | P.T.O |       |        |                      |  |  |  |  |

Continuation



| Particulars                                | Details of actual measurement |                            |                      |    | Contents of area |
|--------------------------------------------|-------------------------------|----------------------------|----------------------|----|------------------|
|                                            | No.                           | L.                         | B.                   | D. |                  |
| Abstract of cost                           |                               |                            |                      |    |                  |
| 5th Year Maintenance bill                  |                               |                            |                      |    |                  |
| 1/1 Restoration of Rain cuts with soil     |                               |                            |                      |    |                  |
| —do—do— all complete job                   |                               |                            |                      |    |                  |
| P-43,                                      | 75.06 m <sup>2</sup>          | cf 3                       | 65.25/m <sup>2</sup> | —P | 27,416.00        |
| 2/2 Making up of Berms/shoulder with       |                               |                            |                      |    |                  |
| soil —do—do— all complete job              |                               |                            |                      |    |                  |
| P-43                                       | 151.72 m <sup>2</sup>         | cf 54.16/m <sup>2</sup>    | —P                   |    | 8,217.00         |
| 3/3 Repair of pot holes with 75mm W.B.D.   |                               |                            |                      |    |                  |
| Gr3 —do—do— all complete job               |                               |                            |                      |    |                  |
| P-45,                                      | 35.20 m <sup>2</sup>          | Limit 35.16 m <sup>2</sup> |                      |    |                  |
|                                            |                               | cf 378.85/m <sup>2</sup>   | —P                   |    | 13,320.00        |
| 4/4 Patch repair over pot holes with       |                               |                            |                      |    |                  |
| pme —do—do— all complete job               |                               |                            |                      |    |                  |
| P-45,                                      | 35.20 m <sup>2</sup>          | Limit 35.16 m <sup>2</sup> |                      |    |                  |
|                                            |                               | cf 306.74/m <sup>2</sup>   | —P                   |    | 10,785.00        |
| 5/5 Patch repair over B.T surface with     |                               |                            |                      |    |                  |
| pme —do—do— all complete job               |                               |                            |                      |    |                  |
| P-45,                                      | 35.23 m <sup>2</sup>          | Limit 35.16 m <sup>2</sup> |                      |    |                  |
|                                            |                               | cf 323.63/m <sup>2</sup>   | —P                   |    | 11,379.00        |
| 6/7 Maintenance of old work (H.P. Culvert) |                               |                            |                      |    |                  |
| —do—do— all complete job                   |                               |                            |                      |    |                  |
| P-39,                                      | 02 Nos                        | cf 1131.64 each            | —P                   |    | 2263.00          |

Continuation C. R. 73,380.00

Continuation