

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year Maint					
Name of work:— Hills Noor Sarou					
Kapsiyewong road to					
Tinlor high					
Agency:— Shashi Prakash					
Agreement no 79530/2018-1					
Actual dt of completion 28.5.20					

①	Restoration of drain			
	Cent			
	2 NO X 2.05m X 30m			1.23m ³
	2 NO X 1.5m X 35m			1.05m ³
	3 NO X 1.25m X 40m			1.5m ³
	6 NO X 0.80m X 40m			1.92m ³
	7 NO X 2.5m X 30m			5.25m ³
	5 NO X 1.85m X 30m			2.77m ³
	4 NO X 1.65m X 30m			1.98m ³
	6 NO X 1.55m X 30m			2.79m ³
	4 NO X 1.90m X 35m			2.66m ³
	8 NO X 1.60m X 35m			4.48m ³
	10 NO X 1.85m X 35m			6.47m ³
	7 NO X 2.5m X 30m			5.25m ³

Continuation—

Total 37.35m³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Hissa Noor-Sopal					
Kapsiy chison road to taluk bishra.					
Assy: Shashi Prakash					
Ass No: 79/SKSD/2018-19					
Actual Date of completion: 28/5/20					
① Restoration of earth cuts - Tse.					
					$2 \times 10 \times 30.00 \times 0.50 \times 0.30 = 90.00$
					Total = 90.00
② Making of beams / shoulder - Tse.					
					$2 \times 10 \times 30.00 \times 0.50 = 300.00$
					Total = 300.00
③ Repair of pot holes with 75mm mesh - Tse.					
					$5 \times 4.50 \times 2.30 \times 0.075 = 3.88$
					Total = 3.88
④ Patch repair over pot holes with 75mm mesh - Tse.					
					$5 \times 4.50 \times 2.30 = 51.75$
					Total = 51.75
⑤ Patch repair over bituminous surface - Tse.					
					Qty same as item ④ = 51.75
					Total = 51.75
⑥ Repair of 10 works (Hydrant pipe co)					
					1 x 2 Nos = 2 Nos.
					Total = 2 Nos.

Continuation

10/6/24
AE