

4th year maintenance

52

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Named work, Kajibagh to Ranipur kaila.					
Assay: Shri Rayjeer Sharma					
Ass no: 66 2018 2018-19					
Actual Date of completion: 30.11.19					
① Restoration of iron chab - T.S.					
8x 10.00 x (0.75 + 0.50)					
$\times 0.30 = 19.80 \text{ m}^2$					
5x 15.00 x 0.60 x 0.30 = 13.50 "					
Total = 33.30 "					
② painting & Berries / Ghantals - T.S.					
2x10 x 30.00 x 0.55 = 330.00 m^2					
Total = 330.00					
③ Repair of Pot holes filled with T.S. mix - T.S.					
1x 06.00 x 3.75 = 22.50 m^2					
1x 4.00 x 3.75 = 15.00,					
Total = 37.50 ",					
④ Patch repair over bit. surface etc.					
1x 06.00 x 3.75 = 22.50 m^2					
1x 4.00 x 3.75 = 15.00,					
Total = 37.50 ",					
⑤ Mending of iron pipe Culment T.S.					
1x 30 Nip. 3 Nip.					
Total = 3 Nip.					
⑥ Painting					
Done on 08/12/23					
AF					
8/12/23					
APC					

Continuation

23

The signature

Continuation