

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Narrow of wood skirting 15' high					
Dhurgam Cheruvu road to					
Ramchandrapur					
Agency: Kumari Ashwiniya & Sons					
Assn: 11/5/20/19-20					
Actual Date of Completion: 20/3/20					
① Restoration of rain chutes etc.					
2x 30.00x0.60x0.30 = 10.80 m ³					
				Total =	10.80 m ³
② Making up of kerbs / shoulder etc.					
2x 30.00x0.75 = 45.00 m ²					
				Total =	45.00 m ²
③ Repairing potholes with work etc.					
1 x 3.60 x 2.50 x 0.075 = 0.68 m ³					
				Total =	0.68 m ³
④ Patch repair over potholes with					
20mm concrete carpet etc.					
1x 3.60x2.50 = 9.00 m ²					
				Total =	9.00 m ²
⑤ Patch repair over potholes etc.					
1x 3.60x2.50 = 9.00 m ²					
				Total =	9.00 m ²
⑥ Lateral noise flow pipe culvert etc.					
1x2 Nos. 3 Nos.					
				Total =	3 Nos.
⑦ White Washing of parapet walls etc.					
				Qty =	62.00 m ²
				Total =	62.00 m ²

Continuation

25/2/24
AE

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of water cistern water tank no. (1) work @ (S2)					
Amt = 10.80 m ² @ 378.29/m ² Cover 7.70 m²					2911 =
(2) Making up Besons / shoulder water tank No. (2) work @ (S2)					
Amt = 45.00 m ² @ 57.13/m ² Cover 14.75 m²					2442 =
(3) Repair & patchwork of brick wall water tank no. (3) work @ (S2)					
Amt = 0.68 m ² @ 8669.06/m ² Cover 0.67 m²					5791 =
(4) Patch repair of concrete water tank no. (4) work @ (S2)					
Amt = 9.00 m ² @ 241.28/m ² Cover 8.91 m²					2154 =
(5) Patch repair of TSCC water tank no. (5) work @ (S2)					
Amt = 9.00 m ² @ 256.29/m ² Cover 8.91 m²					2282 =
(6) Making up HVC pipe CD water tank no. (6) work @ (S2)					
Amt = 3 Nos. @ 1109.67/piece					3329 =
(7) White washing of plaster water tank no. (7) work @ (S2)					
Amt = 62.00 m ² @ 16.13/m ²					1019 =
Total =					14928 =
G.I./CC 10% =					(.) 1993
Total =					17935
<i>[Signature]</i> JST/AC					

Continuation