

1st Year Maintenance

Sch. XLV-Form No.134 20

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:-	solar fall to Pakaniya				
	Porgsy				
Agency:-	S.R. Construction				
Agreement No:-	154/19-20				
	154A/19-20				
Date of order:-	10.2.20				
	14.09.20				
Date of completion:-					
Per agreement:-	22.12.20				
Date of completion order:-	20.12.20				
Date of entry:-	22/12/21				
<u>1/2</u>	Maintenance of earthen shoulder				
	2x4x30.0x1.0				220.0 m ²
				Limited to	202.50 m ²
<u>2/7</u>	Maintenance of dome pipe culverts				2 Nos
<u>3/9</u>	Maintenance of road signs				0.41 km
<u>4/10</u>	Maintenance of KMP and HMP				0.81 km
<u>5/12</u>	Oleic Wash up of Para pot Dells of CD				
	2x2x6.0x0.4				9.6 m ²

Continuation



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2x2x	6.0x	0.60m	-	14.90 ²
	2x4x	0.9x	0.64	-	1.92-9 ²
	2x2x	6.0x	1.39m	-	32.4-9 ²
					58.32-9 ²
			Limited to		72.00-9 ²
22/12/21				22/12/21	
JE/Chhaya					

ABSTRACT OF COST					
1/2	Maintenance of earthen				
	Shoulder				
	Vide TMB Page 29				
	202.50 m ² @ Re 57 = 11655	56 m ²	Re	11655 = 90	
2/7	Maintenance of lum pipe				
	Culverts				
	Vide TMB Page 29				
	2 Nos @ Re 1130 = 2260	67 Each	Re	2261 = 34	
2/9	Maintenance of Road				
	Grass				
	Vide TMB Page 29				
	0.91 km @ Re 1077 = 981	PKM	Re	981 = 90	
	C/U			Re 19359 = 14	

Continuation

