

Particulars	Details of actual measurement				Contents or area
	No.	L	B	H	
With your mind: 17/11					
Name of work: Maint.					
of Road from Shambhugpur					
Dalwa Road to Kani More					
under Ministry No. 13					
Agency: Saitish Kumar					
Agreement No. - 01 WDB of 2018-19					
Agreement Value - Rs. 365438.00					
Actual Date of completion - 21/10/2019					
Maint. Period: - 22/10/22 - 21/10/23					

Record Entry

① Restoration of berms

Berms with soil-mountain etc.

3X3.60X1.10X0.30	= 3.58 m ³
5X4.80X0.75X0.20	= 3.60 "
4X4.30X0.65X0.30	= 3.28 "
6X2.75X0.80X0.30	= 3.96 "
5X3.60X0.15X0.30	= 3.57 "
3X4.65X1.25X0.30	= 4.57 "
5X4.35X1.00X0.30	= 7.28 "
4X3.30X1.20X0.15	= 2.81 "
6X2.75X1.10X0.15	= 2.72 "
2X4.55X0.60X0.25	= 1.37 "
5X4.65X1.20X0.30	= 8.37 "

(Continuation)

Attested

Pritham
12.07.24

Sch. XLV Form No. 134

Particulars	Details of actual measurement			Contracted or area
	No.	L.	B.	
Abstract of Cost of 4th year work 1911				
① Rectification of Raincoats/ Berms with soil. masonry				
58.60 m ³ vide T.M.B. P.No. (16)				
@ Rs. 332.04/m ³ —				Rs. 19391.04
② Making up of Berms/ shoulder, stripping. T/S				
460.92 m ² vide T.M.B. P.No. (17)				
@ Rs. 53.30/m ² —				Rs. 24567.00
③ Repair of pot holes filled with 75 mm				
4.96 m ³ vide T.M.B. P.No. (17)				
@ Rs. 374.31/m ³ —				Rs. 1857.00
④ Patch repair on already filled pot holes with 75 mm — T/S				
68.63 m ² vide T.M.B. P.No. (18)				
@ Rs. 246.79/m ² —				Rs. 16840.00
⑤ Repair to potholes and removal of loose materials trimming of sides etc. T/S				
67.31 m ² vide T.M.B. P.No. (18)				
@ Rs. 263.37/m ² —				Rs. 17727.00
⑥ Maint. of c/s works				
06 Nos. vide T.M.B. P.No. (18)				
@ Rs. 1131.67 (approx.) —				Rs. 6790.00

Attested
Priyam
12.07.24

Scanned with CamScanner