

5th year Maintenance Bill

45.

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:-	LO 27 to				
Name of Agency:-	No. 19 to under LT SNY				
At -	Sri S. J. K. R. R. R.				
At -	S. S. S. S. S.				
Agreement No. & Dated	75/ S. B. D. / 2018 - 2019				
Dated	29/09/2018				
Agreement Rate	10% below				
Date of work start	29/09/2018				
Date of work completion	28/06/2019				
Actual completion date	27/06/2019				

Continuation

5th year Maintenance BH

Abstract 49. of 027

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Vain (cup) Berrys with soil.					
V.T. M.B & P - 46					
Qty - 61.97 m ³					
② R 372.77/m ³					G 23.101 =
② Making up to Berrys & shoulders					
V.T. M.B & P - 46					
Area - 344.25 m ²					
③ R 56.21/m ²					R 19,350 =
③ Maintenance of Hume pipe culverts					
V.T. M.B & P - 47					
Qty - 1 m ³					
④ R 1104.35/eqn R 1104 =					
④ Maintenance of road aggregates.					
V.T. M.B & P - 47					
Qty - 1.350 km					
⑤ R 1067.44/km R 1441 =					
⑤ Maintenance of road cutting of road at 300m from the road					
V.T. M.B & P - 47					
Qty - 0.204 km					
⑥ R 684.17/km R 140 =					

Continuation

C.O. total R 45,136 =

B.F. R 45.136=0

50.

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ Cutting of 6x6mbs from 6x6mbs					
V.T.M.B & P-47					
Qty - 4 Nm					
⑦ R 103.73/each R					415=0
⑦ Cutting of 6x6mbs from 609dway					
V.T.M.B & P-47					
Qty - 2 Nm					
⑧ R 6.42/each R					51=0
⑧ Trimming of gully & weeds from shoulder					
V.T.M.B & P-48					
Area - 1195.31m ²					
⑨ R 2.14/m ²					R 2558=0
⑨ White washing on proper walls of Hume Pipe Culvert					
V.T.M.B & P-48					
Area - 59.04 m ²					
⑩ R 15.51/m ²					R 916=0
⑩ Total R 49.078=0					
Less 10% below R					R 4908=0
Net Bill Amount R					<u>44,168=0</u>
20/06/2024					
SE					