

RAJWANSI TOLA TO MMGSY ROAD
GTSNY

Schedule XLV-Form No. 134

DIVISION

Boroi

KADWA - SUB-DIVISION

984

Measurement Book

BINOD KUMAR SAH

20 1st year Maint Rs - 14230-00
21 2nd year Maint - Rs - 16778-00
22 3rd year Maint Rs - 19454-00

40

[illegible]

(i) Restoration of Rain Cuts
with Soil:

$2 \times 3.50 \times 0.75 \times 0.300 =$	1.57 m^3
$4 \times 4.50 \times 0.95 \times 0.400 =$	$6.84 "$
$3 \times 4.00 \times 0.85 \times 0.350 =$	$3.57 "$
$3 \times 4.80 \times 0.80 \times 0.400 =$	$4.60 "$
$4 \times 4.50 \times 0.95 \times 0.400 =$	$6.84 "$
$3 \times 4.50 \times 0.80 \times 0.400 =$	$4.32 "$
$2 \times 3.50 \times 0.75 \times 0.300 =$	$1.57 "$
$4 \times 2.50 \times 1.00 \times 0.300 =$	$3.00 "$
$3 \times 4.00 \times 1.00 \times 0.350 =$	$4.20 "$
$4 \times 3.50 \times 0.80 \times 0.380 =$	$4.25 "$
$4 \times 5.20 \times 1.00 \times 0.350 =$	$7.28 "$

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
0.6 km wide TMB Fly (4/2)					
@ R8 1067.44/km				R8	640.00
				R8	34695.00
Ass/104. Blaw				R8	3470.00
					31225.00

Man
12/02/24
JE

Man
12/02/24

Man
12/02/24

Man
12/02/24
Executive Engineer
Rural Works Department
Works Division, Barsoi

Material statement

Earth work — 77.16

12/02/24