

Government Of Bihar Office Of The Executive Engineer Rural Works Department, Works Division, Muzaffarpur East-II Mail:-ruralwork2muz@gmail.com & Contact:- 0612-2220866

Letter No: - 1535 8130

Dated: - 10-07-2024

To, Addl.CEO -Cum-Secretary-Cum-Empowered Officer,BRRDA 3rd Floor, Land Development Bank Bhawan, Budh Marg, Patna

Sub:-Regarding issue of allotment in MMGSY-NDB(BRICS)

Respected Sir

With warm regard I am here by requesting to you kindly issue of allotment in MMGSY-NDB(BRICS)

Enclosed: - 1) Road list for required allotment.

2) Utilization Certificate.

Yours Faithfully

Executive Engineer

Rural Works Department

Works Division, Muzaffarpur East-2

+91.8986915781

Rural Works Department Name of Scheme :- MMGSY-NDB(BRICS)

Excutive Ingineer
Rural work Department
Work Division Muz East -2

7

FORM GFR 19-A

Form of utilisation Certification up to month of June-2024 M.M.G.S.Y.-NDB(BRICS)-CFMS

RWD, Works Division, Muzaffarpur East-II

SL. NO.	Name of Scheme	Sanction No & Date with Amount (In Rs.)	Amount Received (In Rs.)	Particulars
1.	Construction of Rural Road under M.M.G.S.Y NDB(BRICS)	Empowered officer B.R.R.D.A Letter No 177	Rs. 31,90,61,288.00 Rs. 31,90,61,288.00 Rs. 31,86,60,545.00	Certified that out of Rs. 31,90,61,288.00 of grant in aid received during the Year 2020-2021-2022-2023-2024 in favour of Executive Engineer R.W.D. Works Division, Muzaffarpur East-II. A sum of Rs. 31,86,60,545.00 has been utilized for the purpose of M.M.G.S.YNDB(BRICS) schemes as given in the margin for which it was sanctioned and that the balance of Rs. 4,00,743.00 remaining unutilized at the end of the period under.
			Rs. 4,00,743.00	
	To		Rs. 4,0 unutiliz	

2. Certified that I have satisfied that the conditions on which the grants-in aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- I. Works have been supervised by Executive Engineer/ Superintending Engineer.
- II. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- III. Construction material has been tested.
- IV. Measurements have been recorded in the MBS and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.
- 3. Physical progress achieved:
- i. Construction of Road Works.
- ii. Construction of CD Works.

Executive Engineer
RWD,Works Division
Muzaffarpur East-2