

I ST ON A/C BILL

1

Name of Work-
Situation of Work-
Agency by which work is executed-
Date of Measurement-
No. and date of agreement

(These four lines should be repeated at the commencement
of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Construction of road					
LCR works from PWD road to					
Khatrisi Kamkaratala.					
Under mmsy (SC)					
Agency - M/s Ravi Construction					
Agreement No - 08/SRD(mmsy-SC)/2019-21					
Agreement value (C) Rs 1,47,16,296/-					
(m) Rs 19,60,368/-					
Date of start : 01/01/2019					
Date of completion 31/12/2019					
Date of measurement 10/02/2019					

-o RECORD MEASUREMENT-

①	Reference pillar 11.0 N.W.
②	Closing & grubbing
	road land - do - do
	as per E.P.I
	$20 \times 30.00 \times 4.00 = 2400.00 \text{ m}^2$ ✓
	$30 \times 30.00 \times 4.00 = 3600.00 \text{ m}^2$ ✓
	$30 \times 30.00 \times 4.00 = 3600.00 \text{ m}^2$ ✓
	$3 \times 30.00 \times 4.00 = 360.00 \text{ m}^2$ ✓
	$1 \times 10.00 \times 4.00 = 40.00 \text{ m}^2$ ✓
	Continuation 10,000.00 m ² ✓
	Or 1.00 Ha

3rd year maintenance bill

53

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	M.	L.	B.	
N/o:- 00110777 formed A.S.D				
km's from phd road				
→ Iskandarpur Karmkar				
→ Tola				
Agency - M/S RARI constn				
Agreement No. 08/SBD/MMCw(50)/				
2019-2020				
Actual Date of completion - 6/8/2020				
Date of Measurement -				

Record entry

(1) Restoration of Roadsides

with soil - as per spec.

47 26.00 x 1.00 x 0.30 - 31.20 m³67 29.00 x 1.00 x 0.30 - 52.20 m³2 x 26.00 x 1.00 x 0.30 - 15.60 m³5 x 30.00 x 1.00 x 0.150 - 37.50 m³2 x 2 x 16.00 x 1.00 x 0.30 - 21.60 m³2 x 2 x 18.00 x 1.00 x 0.30 - 21.60 m³177.30 m³Cmst - 177.20 m³

(2) Making up berms/

shoulder - as per spec.

2 x 2 x 16.00 x 1.10 - 70.40 m³2 x 2 x 20.00 x 1.15 - 92.00 m³2 x 2 x 15.00 x 0.90 - 54.00 m³2 x 2 x 18.00 x 1.00 - 112.00 m³2 x 2 x 30.00 x 1.00 - 120.00 m³Continuation 448.90 m³

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
<u>ABSTRACT OF COST</u>						
<u>Date of entry -</u>						
(1) Restoration of Raincut/ beams CTY videp page						
no. (53) item (1) 177.29 M ³						
(2) Rs 359.74/M ³ → Rs 63741/-						
(3) Making up beams/shoulder						
striping CTY videp NO						
(53) item (2) 843.75 M ³						
(2) Rs 53.70/M ³ → Rs 45307/-						
(4) Repair of pot holes						
Filled CTY videp page no-						
(54) item (3) 10.55 M ³						
→ Rs 2200.33/M ³ → Rs 22507/-						
(5) Patch repair over pot holes with tarmac						
premix carpet mix id						
P.No. (54) item (4)						
175.48 M ² × Rs 219.63/-						
→ Rs 38607/-						
(6) Patch repair over bituminous surface						
CTY videp. NO. (54) item						
(5) 175.78 M ² × Rs 210/-						
→ Rs 3515/- → Rs 54026/-						
(6) Maintenance of tube pipe CTY videp NO. (55)						
item (6) 1100.00 → Rs 110/-						
1104.35/M ³ → Rs 6626/-						

Continuation

Rs - 32835/-

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		B/P	M	334521	
less 1.27% as per agreement (→)				42480	
				Rp 330273	
Survey 1068		Survey 1068		DAO CSP Hukka 8724	