

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w - const. of road/ farm Din dayal gangi pul to Korbi more					
Agency - Kuman Aranjit Sehgh					
App. NO - SB D/58) 20-8-2019					
Actual Date of comp - 05/3/2020					
Date of Entry - 05/3/2020					
<u>1</u>) Restoration of drain cut (5.1) to <u>10x3m</u> <u>10x3m x 5m = 150 m³</u> <u>10 x 5m x 5m x 0.300m = 75 m³</u>					
<u>2</u>) making up of Berm (5.2) to <u>all comp</u> <u>27 x 18m x 1.2m = 583.2 m²</u> <u>2 x 2.5m x 1.2m = 6 m²</u> <u>586.2 m²</u>					
<u>3</u>) Repair of root hole filled (5.3(i)) with 75mm ds <u>all</u> <u>76 x 13m x 1.2m x 0.075m = 88.92 m³</u>					
<u>4</u>) Patch repair over (5.3(ii)) Bituminous layer <u>all</u> <u>53 x 1.2m x 1.4m = 89.04 m²</u>					
Continuation					

Sch. XLV-Form No. 134