

07 MBD/2019-20

Baisa Rud Road to Mathiya Teta
(MMDSP-WB)

Measurement Book

1621

Schedule XLV-Form No. 134

Baisi

DIVISION

Baisa

SUB-DIVISION

Ajam construction

1st year Maintenance

1

Name of Work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement -

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maint of Rd from					
Beisa Road Road to Hargis To 12					
Agency - A/m Construction					
Agreement No - 07MBD/2019-20					
Date of Commencement - 27/12/19					
Actual Date of Completion - 23/01/20					
Record Entry					
① Restoration of mounds/berms with soil, no m.					
	4x6.00m	0.850m	0.30m		6.12m ³
	6x3.75m	0.900m	0.30m		6.08m ³
	3x10.50m	0.800m	0.30m		7.56m ³
	3x7.50m	0.850m	0.30m		5.74m ³
	4x6.50m	0.750m	0.30m		5.85m ³
	3x11.00m	0.700m	0.30m		6.93m ³
	3x9.00m	0.800m	0.30m		6.48m ³
	3x8.50m	0.950m	0.30m		7.27m ³
	2x14.50m	0.900m	0.30m		7.83m ³
	3x7.00m	1.000m	0.30m		6.30m ³
	4x10.00m	0.700m	0.30m		8.40m ³
	3x9.50m	0.700m	0.30m		5.99m ³
	4x5.50m	0.900m	0.30m		5.94m ³
	3x11.50m	0.750m	0.30m		7.76m ³

Continuation

96.25m³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				21 F	94.25 M ²
	3x10.50 M	0.90 M	0.30 M		8.51 M ²
	2x15.00 M	0.85 M	0.30 M		7.65 M ²
	3x7.60 M	0.70 M	0.30 M		5.67 M ²
	5x5.50 M	0.85 M	0.30 M		7.01 M ²
	3x10.00 M	0.75 M	0.30 M		6.75 M ²
	2x13.00 M	0.95 M	0.30 M		7.41 M ²
	2x12.50 M	1.05 M	0.30 M		7.88 M ²
	2x13.50 M	0.85 M	0.30 M		6.89 M ²
				Total Qty.	152.02 M ²
				Limit Qty.	151.88 M ²

(22) Making up of beams/shoulder for coping excess soil from the shoulder.

3x	17.00 M	0.930 M		48.45 M ²
3x	19.00 M	0.850 M		48.45 M ²
4x	14.00 M	0.700 M		39.20 M ²
3x	21.00 M	0.800 M		50.40 M ²
2x	29.00 M	0.900 M		52.20 M ²
3x	16.00 M	0.850 M		40.80 M ²
4x	11.00 M	0.900 M		39.60 M ²
4x	17.00 M	0.750 M		51.00 M ²
3x	22.00 M	0.850 M		56.10 M ²
3x	27.00 M	0.750 M		60.75 M ²
2x	30.00 M	0.850 M		51.00 M ²
3x	15.00 M	0.950 M		42.75 M ²

Continuation

C/O 580.70 M²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				61 E	580.7014 ²
	3x	20.001 ¹ / ₂	0.8001 ¹ / ₂		48.0001 ¹ / ₂
	2x	26.001 ¹ / ₂	0.7001 ¹ / ₂		39.001 ¹ / ₂
	3x	14.001 ¹ / ₂	0.9001 ¹ / ₂		37.8001 ¹ / ₂
	3x	23.001 ¹ / ₂	0.7501 ¹ / ₂		51.751 ¹ / ₂
	3x	21.501 ¹ / ₂	0.8001 ¹ / ₂		57.601 ¹ / ₂
	3x	19.501 ¹ / ₂	0.7001 ¹ / ₂		40.951 ¹ / ₂
	2x	28.001 ¹ / ₂	0.7501 ¹ / ₂		42.001 ¹ / ₂
				Totally	891.801 ¹ / ₂
				Limitly	843.731 ¹ / ₂
(3/4) patch repairs over potholes					
with M.M. sec/surfacing					
	2x	2.901 ¹ / ₂	1.2501 ¹ / ₂		7.251 ¹ / ₂
	2x	2.251 ¹ / ₂	1.3001 ¹ / ₂		7.151 ¹ / ₂
	3x	1.501 ¹ / ₂	1.4501 ¹ / ₂		6.531 ¹ / ₂
	3x	1.251 ¹ / ₂	1.2501 ¹ / ₂		4.691 ¹ / ₂
	2x	2.251 ¹ / ₂	1.4001 ¹ / ₂		6.301 ¹ / ₂
	3x	2.001 ¹ / ₂	1.0501 ¹ / ₂		6.301 ¹ / ₂
	2x	2.501 ¹ / ₂	1.3501 ¹ / ₂		6.751 ¹ / ₂
	3x	1.751 ¹ / ₂	1.3001 ¹ / ₂		6.821 ¹ / ₂
	3x	1.901 ¹ / ₂	1.2501 ¹ / ₂		7.121 ¹ / ₂
	2x	3.251 ¹ / ₂	1.1001 ¹ / ₂		7.151 ¹ / ₂
	2x	1.201 ¹ / ₂	1.2501 ¹ / ₂		4.251 ¹ / ₂
				Totally	70.311 ¹ / ₂

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4/6) Maintenance of H.P. Culvert ————				4.00 Nos.	
(5/7) Maintenance of C/L.B Culvert ————				2.00 Nos.	
(6/8) Maintenance of Road Sign ————				0.32 Km	
(7/9) Maintenance of road 2nd Km stone ————				0.39 Km	

(8/10) i, Cutting of branches of trees and shrubs ————				5.00 Nos.	
(9/10) ii, Cutting of shrubs from Roadway ————				25.00 Nos.	
(10/10) iii, Trimming of grass and weeds					
1x	1.50 M	1.05 M			1.58 M ²
1x	1.50 M	0.75 M			1.13 M ²
1x	1.50 M	0.80 M			1.20 M ²
1x	1.50 M	0.90 M			1.35 M ²
1x	1.50 M	0.85 M			1.28 M ²
1x	1.50 M	1.00 M			1.50 M ²
1x	3.00 M	1.10 M			3.30 M ²

Total 11.34 M²

Continuation