

Bijay Kumar Yadav

Name of Road:- House of Bidyanand Das
To M.B. Road (B.T.S.N.Y.-2018-2019)
Shedule XLV Form No. 134.

DIVISION

SUB-DIVISION

Measurement Book

- 669
10-9-18

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4 th year maintenance Bill					
name of work - Construction and maintenance of road from house of Bhalga Mand Dag to MmbSY road.					
Item - GTSKY					
Agency - Bofay Kumar Yadav					
Agreement No -	380/2018-19				
Date of Commence -	26/09/2018				
Date of Actual completion -	21/01/2019				
Date of Entry -	07/01/23				
① Restoration of ruin work					
- - all complete job					

5x	13.5	0.70	0.30	=	13.65m ³
9x	11.0	0.60	0.30	=	17.82m ³
6x	9.0	0.60	0.30	=	9.72m ³
5x	16.50	0.65	0.30	=	16.09m ³
					57.28m ³

② maintenance of earthen

Shoulder - all complete job

5x	15.0	0.50	=	37.50m ³
9x	18.0	0.60	=	97.20m ³
13x	11.0	0.60	=	85.80m ³
6x	21.0	0.55	=	69.30m ³
8x	7.0	0.50	=	28.00m ³
				317.80m ³

Continuation

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5 th year					maintenance Bill
Name of work -	Construction and main-				
tenance	of road from house of				
Bidya Nand Das to M. M. Das					
Head -	GT S. No.				
Agency -	Bidya Kumar Yadav				
Agreement No -	SBD/2018-19				
Date of Commence -	26/09/2018				
Date of Actual Completion -	12/01/2019				
Date of Entry -	03/01/24				
① Restoration of rain cut					
— — all complete job					

5x	14.00x0.60x0.30 =	12.60m ³
9x	11.00x0.60x0.30 =	17.82m ³
11x	8.00x0.65x0.30 =	17.16m ³
9x	10.00x0.60x0.30 =	16.20m ³
		63.78m ³
② Maintenance of earthen		
shoulder -	all complete job	
7x	16.00x0.50 =	56.00m ³
11x	13.00x0.55 =	78.65m ³
9x	21.00x0.55 =	103.95m ³
8x	14.00x0.50 =	56.00m ³
10x	12.50x0.50 =	62.50m ³
		357.10m ³

Continuation

Continuation