

1st year Maint. work

11

Sch. XLV—Form No. 134

Sch. XLV—Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
N/W-Maintenance of Road from Fakarabad to MMUS Road Agency - Sri Pintu Kumar Singh Ag.No - SG/SBD/2021-22 D/O/S - 03.01.2022 D/O/A/c - 26/11/2022					

1) Restoration of drain cuts

1x	4.0x	1.05x	0.25 =	1.05	✓
1x	3.0x	0.95x	0.25 =	0.71	✓
1x	8.0x	1.25x	0.30 =	3.0	✓
2x	4.50x	1.10x	0.25 =	2.47	✓
1x	5.5x	0.85x	0.26 =	1.21	✓
1x	10.0x	0.58x	0.30 =	1.68	✓
Total =				10.12 m ³	✓

2) Making up Berm/shoulder

2	3.50	$\times 1.50 =$	10.5	✓
4	2.0	$\times 1.50 =$	12.0	✓
4	4.0	$\times 1.23 =$	19.68	✓
1	2.25	$\times 1.20 =$	2.70	✓
1	2.0	$\times 1.20 =$	2.60	✓
2	5.50	$\times 0.75 =$	8.25	✓
Total			$= 55.73 \text{ m}^2$	✓

3) Maint. of Road sign

				=	0.02 km	✓
4) Maint. of 200m/KM stone				=	0.02 km.	✓

Continuation

4/11/23
AN

Abstract of Conf

12

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
1) Restoration of surface drain cuts					
Qty = 10.12 m ³ VT M B P-11					
Qty 404 = 06/m ³ — B					408920
2) Making up of Beam/shoulder					
Qty = 55.73 m ³ VT M B P-11					
Qty 60 = 28/m ² — B					335920
3) Maint. of Road/side					
Qty = 0.02 km VT M B P-11					
Qty 1104 = 58/km — B					2220
4) Maint. of 100m / km long					
Qty = 0.02 km VT M B P-11					
Qty 6472 = 51/km — B					1320
					748320
Add 1.1. LC					7520
Add 12% GST					89820
					5620
Add S.F					5620
					815620
					851220
					26320
Deed. 3.11 % below (1)					26520
					824720
					819320
Road is maintained					
Road is in good condition					
					41143
					76

Continuation