

L041 to Meghna dik II (SC) Ministry

Ag.No. 48 SBD/2020-2021

Schedule XLV Form No. 134.

Ag value (71.5834) 0.00% below

Sheryhat i _____ DIVISION

Amias _____ SUB-DIVISION

M/S Naa Shanti Const.

Measurement Book

1292

2nd Year Maintenance bill

36

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work -	consolidation of Road from				
	Lyn to Meghabadih				
Agency -	MAA Shanti Consolidation				
Agreement No -	48/SRD/2020-21				
Item (1)	Restoration of Raincurb				
	10X	4.10X	1.10X	0.30 =	13.53 m ²
	9X	5.50X	1.15X	0.250 =	14.23 m ²
	11X	4.80X	1.20X	0.300 =	19.00 m ²
	12X	1.10X	0.90X	0.300 =	3.56 m ²
	10X	3.10X	0.800X	0.300 =	7.44 m ²
					57.76 m ²
				or	57.17 m ²
Item (2)	Mowing up to Berms/				
	Shoulder				
	12X	5.40X	1.10	=	71.28 m ²
	11X	6.10X	1.15 =		77.16 m ²
	10X	4.80X	1.20 =		57.60 m ²
	9X	3.50X	1.10 =		34.65 m ²
	8X	2.40X	1.20 =		23.04 m ²
	8X	5.70X	1.10 =		50.76 m ²
					318.89 m ²
Item (3)	Repair of Potholes				
	filled with 75 mm				
	1X	0.45X	0.30 =		0.13 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
item (9) cutting of branches of Tree and shrubs				— 6 Hb	
item (10) cutting of shrubs from road way				— 940 Hb	
item (11) Trimming of grass and weeds					
	2x 10x	30x 1.10 =			660 m ²
	2x 20x	30x 1.20 =			1440 m ²
					<u>2100 m²</u>
item (12) white washing of parapet walls of C-D works					
	2x 3x	6.00x 0.400 =			14.40 m ²
	4x 3x	6.00x 0.600 =			43.20 m ²
	3x 4x	0.400x 0.600 =			2.88 m ²
					<u>60.48 m²</u>
item (13) patch repair over Bituminous surface					
	15x 1.60x	1.10 =			26.40 m ²
	12x 1.40x	0.900 =			15.12 m ²
	4x 0.800x	0.500 =			1.60 m ²
					<u>43.12 m²</u>

A. J. J. J.
22/06/23
R

Continuation

ABSTRACT OF COST

39

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1/15-1A) restoration of Rain cuis					
V.T.M.B.P.N. - (36)					
item (1) —				57.12 m ³	
Q 386.14 / m ³ —					22276=
(2/15-2U) Maching of Bays/ Shoulder					
V.T.M.B.P.N. - (36)					
item (2) —				313.89 m ²	
Q 5736 / m ² —					18005=
(3/15-5) REPAIR of pot holes filled with Isr					
V.T.M.B.P.N. - (36)					
item (3) —				0.13 m ²	
Q 9428.09 / m ² —					1226=
(4/15-3U) Patch repair over potholes with Isr					
V.T.M.B.P.N. - (37)					
item (4) —				44.13 m ²	
Q 242.64 / m ² —					10708=
item (5) Patch repair over Ridgelines surface					
V.T.M.B.P.N. - (38)					
item (5) —				43.12 m ²	
Q 259.75 / m ² —					11200=

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(6/15-10-6) Filling of cracks and joints					
V.T.M.B.P.No. (37)					
item no (5) - 940 m					
Q 3.96/m —				5	3722.00
(7/15-70) Maintenance of H.P Culvert					
V.T.M.B.P.No. (37)					
item no (6) - 3 H					
Q 1130.67/H —					3392.00
(8/15-9) Maintenance of Road sign					
V.T.M.B.P.No. (37)					
item no (7) - 0.94 km					
Q 1077.81/km —					1013.00
(9/15-11) Maintenance of 200m and km stone					
V.T.M.B.P.No. (37)					
item no (8) - 0.94 km					
Q 628.22/km —					591.00
(10/15-12-02) Cutting of branches of tree and shrubs					
V.T.M.B.P.No. (38)					
item no (9) - 6 H					
Q 109.74/H —					658.00
(11/15-12-11) Cutting of shrubs					

Continuation

Continuation