

19M1659 / 101 to Adaulichark.

GEN

Ag No-15880/19-20

Schedule XIV-Form No. 134

0.117. below

Rud (w) div. Chergkahi DIVISION

MB No-1096

Amas SUB-DIVISION

M/s maa shanti Court

MEASUREMENT BOOK

Ag value - 66.60034 lach

20.8.19

to

19.4.2020

3rd Year Maintenance bill

58.

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - TO, TO Adaulidok					
Agency - Mao Shanti Construction					
Agreement No - 15 SSPD/2019-20					
Item-①	restoration of Raibuts/ Berms with soil				
	10	5.10	1.15	0.30	17.59 m ³
	9	4.80	1.20	0.280	12.96 m ³
	11	6.20	1.25	0.30	25.57 m ³
	8	4.20	1.10	0.28	9.24 m ³
					65.36 m ³
					Limit - 63.72 m ³
Item-②	making up of Berms shoulder				
	15	3.90	1.20		70.2 m ²
	14	4.50	1.15		72.45 m ²
	10	6.10	1.25		76.25 m ²
	13	5.50	1.10		78.65 m ²
	10	5.10	1.00		51.00 m ²
					348.55 m ²
Item-③	Repair of Pot holes filled with J82m w.B.M				
	1	0.450	0.40		0.18 m ²
Item-④	patch repair over pot holes				
	10	2.20	1.10		24.2 m ²

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item-9	Maintenance of Road				
	Siph-	0.91m			
Item-10	Maintenance of 2m and 1cm slope				
		0.91m			
Item-11	Cutting of branches of Tree and shrubs				
	1x6 = 6 hp				
Item-12	Cutting of shrubs from road				
	1x899 = 899 hp				
Item-13	Trimming of Grass and weeds				

	2x 29x 30x 1.15 = 2001 m ²			
Item-14	White wash of parapet wall			
	10x6.00x0.40 = 24.00 m ²			
	20x6.00x0.600 = 72.00 m ²			
	20x0.40x0.60 = 4.80 m ²			
				100.80 m ²
A. Kumar 13/10/23 2				

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	' B.	D.	
	<u>ABSTRACT OF COST</u>				
1/	Restoration of Raincups				
	V.T.M.B.P.No. - (58)				
	item no (1) - 63.72 m ²				
	at 380.58/m ² — 24251.30				
(2/)	making up of Berms				
	Shoulder				
	V.T.M.B.P.No. - (58)				
	item no (2) - 348.55 m ²				
	at 58.37/m ² — 20345.20				
(3/18.5)	Repair of pot holes				
	filled with 7cm w.B.M				
	V.T.M.B.P.No. - (58)				
	item no (3) - 0.18 m ²				
	at 10834.33/m ² — 1950.00				
(4/18.32)	Patch repair over				
	pot holes				
	V.T.M.B.P.No. - (58)				
	item no (4) - 63.21 m ²				
	at 299.17/m ² — 18911.30				
(5/)	Patch repair over				
	Bituminous surface				
	V.T.M.B.P.No. - (59)				
	item no (5) - 61.88 m ²				
	at 303.30/m ² — 18768.20				
(6/18.32)	Filling of cracks				
	and joints				
	V.T.M.B.P.No. - (59)				
	item no (6) - 899.20				

Continuation

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(7/15/7) Maintenance of C.D works (H.P culvert)	as	4.69/m			4216 ⁰⁰
V.T.M.B.P.No-(59)					
item no (7) - 5 Ho					
(8/8/17) Road Marking	as	1117/10			5585 ⁰⁰
V.T.M.B.P.No-(59)					
item no (8) - 179.8 m ²					
(9/15/9) Maintenance of Road	as	852.00/m ²			153190 ⁰⁰
Sign					
V.T.M.B.P.No-(60)					
item no (9) - 0.9 km					
(10/15/70) Maintenance of 20cm and 1m stone	as	1024.51/m			967 ⁰⁰
V.T.M.B.P.No-(60)					
item no (10) - 0.90 km					
(11/15/20) cutting of branches of Tree and shrubs	as	643.75/m			579 ⁵⁰
V.T.M.B.P.No-(60)					
item no (11) - 6 Ho					
(12/15/21) cutting of shrubs from road way	as	106.52/m			639 ⁰⁰
V.T.M.B.P.No-(60)					
item no (12) - 899 m					
Continuation	as	6.54/m			5879 ⁰⁰

Continuation