

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	H.	
Work at work maintenance at					
road from Kull road down canal					
to shivnaha					
Agency - Raju Kumar Singh					
Agg. No. - 06300 - 2018-19					
Date of commencement - 05-09-2018					
Date of completion -					
Date of entry -					

①	Restoration at minor culvert				
	do			all	
	2.0 x 20.00 x 2.25 x 0.3 =				40.5
	2.0 x 26.00 x 2.25 x 0.3 =				35.1
					75.6
②	Maintenance at earthen				
	shoulder	do		all	
	2.00 x 30m x 2.25 =				135
	2.00 x 30m x 2.25 =				135
	2.00 x 30m x 2.25 =				135
	1.00 x 12m x 2.25 =				27
					432m ²
③	Maintenance at house pipe				
	culvert	do		all	

Continuation

Continuation

24 Dec 1944