

Dijar Kala to Toq

Schedule XLV-Form No. 134 (SC)

E.E. R.W.D. (W)

DIVISION

GIAVA

A.E. R.W.D. (W)

SUB-DIVISION

(WAZIRGANJ)

**MEASUREMENT BOOK**

3149

Name of Work-

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1st	on	A/C Bill		

Name of work: Const of rural road  
from Oriyarkhole To Taty  
under MNGSY (SC)

Agency: Sanjay Kumar  
Aglt No: 159/MNGSY/SBD/2022-23

Dow: 14-2-22

Toc: 13-2-23

Date of measurement: 28-8-22

① Const of ref & working  
BMZ dredge

1.50 KM

② cleaning & grubbing  
of road (6m) wide

$$10 \times 30 \text{ m} \times 7 \text{ m} = 2100 \text{ m}^2$$

$$10 \times 30 \text{ m} \times 7 \text{ m} = 2100 \text{ m}^2$$

$$10 \times 30 \text{ m} \times 7 \text{ m} = 2100 \text{ m}^2$$

$$10 \times 30 \text{ m} \times 7 \text{ m} = 2100 \text{ m}^2$$

$$10 \times 30 \text{ m} \times 7 \text{ m} = 2100 \text{ m}^2$$

10500 m<sup>2</sup>

or 1.05 Hect

40

Ist Year Maintenance Bill

41

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Const. of road from village Kala to Talwander					
MMSY (sq.)					
Agency - Sanjay Kumar					
Agt. No - 159   MMSY   SBP   2002-23					
DOW - 14.02.03					
TOC - 13.02.03					
(1) Restoration of embank.					
					75.9943
(2) Marking up of embank. Shoulder.					
					42.9.164
(3) Repair of pot hole.					
					0.1143
(4) Patch repair over pot hole.					
					35.1844
(5) Patch repair over bituminous surface					
					35.1842
(6) Crack sealing filling of cracks.					
					150.14

Continuation



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
(1) Restoration of a coin cutter.	P/41	75.99 M <sup>3</sup>			
	C	404=06	b=	30705=00	
(2) Marking up of boundaries/ shoulder.	P/41	42x.16 M <sup>2</sup>			
	C	60=28	b=	25448=00	
(3) Repair of Pot hole	P/41	99.64=99	b=	1041=00	
	C	99.64=99	b=	1041=00	
(4) Patch repair over Potholes.	P/41	35.18 M <sup>2</sup>			
	C	246=63	b=	8676=00	
(5) Patch repair over B terminals	P/41	35.18 M <sup>2</sup>			
	C	264=05	b=	9289=00	
(6) Cracky Sealing filling of cracky.	P/41	1501.00 M <sup>2</sup>			
	C	3=25	b=	5779=00	

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(7) (1)	Maint. of C.I.D Works				
P/42	4.65M <sup>2</sup>				
	C 1166 = 58	b = 4666 = 00			
(8) (2)	Maint. of C.I.D Works				
P/42	2.50M <sup>2</sup>				
	C 2394 = 96	b = 4790 = 00			
(9) (4)	Maint. of road				
	S. 199.				
P/42	1.50K <sup>2</sup> m				
	C 1104 = 59	b = 1657 = 00			
(10) (5)	Maint. of 200m L				
	Keg strong.				
P/42	1.50K <sup>2</sup> m				
	C 643 = 17	b = 965 = 00			
(11) (6)	Cutting. of banchay				
P/42	4.00M <sup>2</sup>				
	C 113 = 64	b = 455 = 00			
(12) (7)	Cutting. se sawing.				
P/42	150 1.00M <sup>2</sup>				
	C 6 = 98	b = 10477 = 00			
(13) (8)	Trimming of grass				
	and weeds				
P/42	33.78.00M <sup>2</sup>				
	C 3 = 33	b = 7871 = 00			

Sch. XLV-Form No. 134