

Almora  
Schedule XLV-Form No. 134

प्रकाशन द्वारा प्रियोग के लिए नियमित रूप से उपलब्ध है।

E. E. R. W. D. (L)

DIVISION  
P.M.A.

A. E. R. W. D. (L)

SUB-DIVISION  
B.C.D.H.A.-A

Measurement Book

On Jay Kr (1941)

BODH GAYA

3072

1.

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
	I	Start Atc	P>11		
Name of work (part of road) (any)					
From 1 To grime Tolz					
To Machinaz via Koshibg					
Under railway (G)					
Agency: Sanjup Board					
Agreement No: 92117/2021/Gen/SDP/20-21					
Date 27.01.21					
T.O.C. 26.01.22.					
Date of measurement: 16-6-21					

(1) Cost of ref &amp; running

Benz diesel oil

1.544 Km

(2) Cleaning 2 grouting

Wt ~ 20 kg (1st) diesel

$$20 \times 30.00 \times 7.00 = 4200 \text{ cm}^3$$

$$20 \times 30.00 \times 7.00 = 4200 \text{ ml}$$

$$10 \times 30.00 \times 7.00 = 2100 \text{ cm}^3$$

$$2 \times 22.00 \times 7.00 = 308 \text{ cm}^3$$

$$10808.00$$

or 1.080 Hect

C10

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work -	(Conc - of road) road for Macadam Total length 210m via Kestha under Munshi (400)				
Agency -	Santosh Kumar				
Agt No -	92144454 / 600180180-21				
Date -	27.01.21				
T.O.C -	26.01.22				
A.D.C -	24.01.22				
Date of measurement -					
(1) Restoration of original culs	Rectification of original culs				
	93.3043				
(2) Making up of Broken/ shoulder.	Making up of Broken/ shoulder.				
	521.10M <sup>2</sup>				
(3) Repair of pot holes	Repair of pot holes				
filled -	0.2242				
(4) Patch repair over Potholes.	Patch repair over Potholes.				
	72.3842				
(5) Patch repair over Bituminous.	Patch repair over Bituminous.				
	72.3842				
(6) Crack sealing filling	Crack sealing filling				
	1544.00H				

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of Cost					
(1/1) Restoration of drain					
Cub.					
P/52	93.80 H <sup>3</sup>				
Q 404=06		R = 3790/-=00			
(2/2) Making up of boundary.					
P/52	521.10 H <sup>1</sup>				
Q 60=2.8		R = 31412=-00			
(3/3) Repair of pot hole.					
P/52	0.22 H <sup>2</sup>				
Q 8.65 3=56		R = 1904=-00			
(4/4) Patch repair in road					
Pot hole.					
P/52	72.38 H <sup>2</sup>				
Q 228=65		R = 16550=-00			
(5/5) Patch repair in boundary					
Surface.					
P/52	72.38 H <sup>1</sup>				
Q 244=76		R = 17716=-00			
(6/6) Concrete scaling - filling					
of crack.					
P/52	154.4.00 H				
Q 3=71		R = 5728=-00			
(7/11) Main & C/D work.					
P/53	3.00 H <sup>0</sup>				
Q 1160=58		R = 3500=-00			

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8/12) Maint of C/D Works					
P/54	2.00 N.Y				
	@ 2394=96	b= 4790=00			
(9/14) Maint of road Signs					
P/54	1.54 km				
	@ 1104=59	b= 1701=00			
(10/15) Maint of 2000 sq ft m					
	Stone.				
P/54	1.54 km				
	@ 643=17	b= 990=00			
(11/18) Trimming of grass and weedy.					
P/54	34.7440041				
	@ 2=33	b= 8094=00			
(12/17) White washing of purple walls.					
P/54	10.8.0041				
	@ 16=90	b= 1764=00			
		b= 1320.50=00			
(13/16) cutting of branched trees					
P/54	9.00 N.Y				
	@ 113=64	@ 102.3=00			
(14/17) cutting of shrub from road way.					
P/54	154.4.00 N.Y				
	@ b=98	b= 16777=00			
		b= 1438.50=00			

Sch. XLV-Form No. 134