

1st year maintenance.

28

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work:-	main ⁿ of Road from				
	Baru of Bankat RM				
	14 MANIKPUR RMGS Hak.				
N/Agency:-	Shree Anandh mittala				
	cons. pvt. LTD. MYZ.				
Agg. No:-	375 SBD / 2021-22				
D.O.S-	12.	01.	2022		
A.D.O.C -	12.	12.	2022		
	Date of measurement.				

(1)	Restoration of rain				
	cut - do - do -	e/5			
	11x	11.00x	0.90x	0.30 =	32.67m ³
	12x	12.00x	0.70x	0.30 =	30.24m ³
	13x	14.00x	0.80x	0.30 =	43.68m ³
	11x	12.00x	0.60x	0.30 =	23.76m ³
	12x	11.00x	0.80x	0.30 =	31.68m ³
	13x	12.00x	0.70x	0.30 =	32.76m ³
	12x	12.00x	0.80x	0.30 =	34.56m ³
				Qty =	229.35m ³
(2 1/2)	main of earthen				
	Shoulder - do - do -	e/2			
	12x	11.00x	0.80	=	105.60m ²
	11x	12.00x	0.90	=	118.80m ²
				Qty =	224.40m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B/P	RS =	190649=00
(4/5) main of Hume pipe					
culvert - do - E/L					
TMB page (29/4) Qty 2.00 m					
@ Rs. 1182.79/each - RS =					2366=00
(5/6) main of slab type					
culvert - do - E/L					
TMB page (29/5) Qty 3.00 m					
@ Rs. 2426.45/each - RS =					7279=00
(6/8) main of 200mm					
km Stone - do - E/L					
TMB page (30/6) Qty 4.62 m					
@ Rs. 778.19/each - RS =					3595=00
				RS =	203889=00
Add 12% T				RS =	24467=00
Add 1% C				RS =	2039200
				RS =	230395=00
Limit as per Quoted Rate					
				RS =	20457=00
Sub Total 24					
JE					