

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
1 Name of work: Mullupur Tepri mukhya sadak to mullupur utter under mmsy					
2. Agency: Subash Infrastructure Pvt. Ltd.					
3. Agreement No: 75/SBD/2020/2021					
4. Actual dt of completion: 22-09-2021 — work done —					
① Restoration of drain cuts is ① with soil - do for					
1x 30.0 x 0.65 x 0.30 = 5.85					
1x 30.0 x 0.70 x 0.30 = 6.30					
2x 30.0 x 0.68 x 0.30 = 12.24					
2x 30.0 x 0.60 x 0.30 = 10.80					
2x 30.0 x 0.58 x 0.30 = 10.44					
1x 18.60 x 0.60 x 0.30 = 3.348					
1x 20.60 x 0.59 x 0.30 = 3.676					
2x 30.0 x 0.50 x 0.30 = 9.00					
2x 30.0 x 0.52 x 0.30 = 9.360					
					Qty = 61.624m ³
					Say Qty = 60.75m ³
② maintenance of earthen is 2 shoulder cut for					
2x 3x30.0 x 0.65 = 117.0					
1x 2x50 x 0.60 = 12.30					
1x 18.50 x 0.68 = 12.58					
2x 30.0 x 0.70 = 42.0					
					C.O. Qty = 183.88m ²

Continuation

P.710

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					BFB 142578 = ∞
Add 1% labor + 1%					1426 = ∞
Add 12% C.S.T. + 1%					17709 = ∞
Perigon 1024 gcfce					286 = ∞
					B 161399 = ∞
Less 17.95% below					B 28971 = ∞
					B 132428 = ∞

Ram
24.09.2023

J-E

5/10/23
26

material statement

① Earth	—	111.383 m ³
② Bitumen 50	—	98.448 kg
③ Stone chips	—	1.265 m ³

Ram
24.09.2023

J-E

5/10/23
26

Continuation