

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - main of road from Pokrohi Bitch road to Gadiyoni do/g					
Agency - Madhuwani construction					
Agreement No - 62500/morlay/19-20					
Actual Completion 31.10.2020.					
<u>Record Entry</u>					
1) Restoration of main					
cut 1.8% slope					
— do —					
6x	6.90	x	0.90	x	0.30 = 11.18
8x	4.90	x	0.95	x	0.30 = 11.17
6x	5.70	x	1.10	x	0.30 = 11.29
7x	5.90	x	0.95	x	0.30 = 11.78
8x	6.60	x	0.85	x	0.30 = 13.46
7x	5.90	x	1.00	x	0.30 = 12.39
9x	6.30	x	1.10	x	0.30 = 18.71
Total =					89.96
2) main of earthen					
shoulder - do.					
2x	6x	5.90	x	1.10 =	77.88
2x	7x	4.40	x	0.65 =	40.07
Total =					117.92
3) Repair of pot					
holes - do.					
6x	4.10	x	0.85	x	0.20 = 20.91

Continuation: