

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, महनार (वैशाली)

पत्रांक 1426(3480)

/महनार/दिनांक :- 29/07/24

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, महनार

सेवा में,

नोडल पदाधिकारी, MR (3054)
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय :- नई अनुरक्षण निति-2018 MR (3054) के तहत निर्मित पथ की राशि
की अधियाचना पत्र समर्पित करने के संबंध में।

महाशय,

उपरोक्त विषय के संदर्भ में नई अनुरक्षण निति-2018 MR (3054) से
निर्मित पथ के लिए राशि की अधियाचना विहित प्रपत्र में समर्पित की जा रही है।

विदित है कि अधियाचित पथ का कार्य संतोषप्रद है। अधियाचित पथ
में आवंटन देने की कृपा की जाये।

अनु०:-1, अधियाचना विहित प्रपत्र।

विश्वासभाजन

[Signature]
29/7/24

[Signature]
29/7/24
कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, महनार
29.7.24

MIR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division. Mahnar

Sl.No	Package No	Name of the Road (English)	Project ID as per MIS	Administrative Approval (AA) Letter no Date	Administrative Approval		Agreement Amount		Agreement No & Date	Date Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/Km)	Thickness of Bitumen Layer / Thickness of PCC (in mm)	Value of Bitumen Content in Percentage/ Grading of concrete	Previous Total Allotted Amount (in Lakh)	Up to Date Expenditure as per MIS	Requisition against work done (in Lakh)	Remarks
					Length (in KM)	Amount of Lakh	Initial Rectification and Surface Renewal (in Lakh)	Five Years Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/VAM AHZ2/0001	P.M.G.S.Y. Road Near Faratu Wala Mandir Via Sadebad Middle M.M.G.S.Y.School	31507712016	03.06.2022	1.05	71.65000	57.67796	7.48190	02/MBD/23-23 16.07.2022	06.04.2023	21.01.2023	-	160 mm	M30	57.16021	55.71286	0.35632	Completed
2	RM/VAM AHZ2/0034	Chaugabo To Bhunihar Tola	31507712050	Lt. No-1905 27.03.2023	2.85	181.944	123.61921	24.03361	28/MBD/23-24 29.08.2023	28.05.2024	-	3326	B.T-25 mm PCC 160 mm	Bitumen-5.023% PCC M-30	122.00000	122.00000	1.09479	
3	RM/VAM AHZ3/0014	Kargil Gate Se Kunbpur Sangat Tak Durgamandir Tak	315771902725	Lt. No-2484 21.11.2022	3	296.33	223.03069	22.26176	6/MBD/23-24 04.04.2023	03.01.2024	-	3288	PCC 160 mm	PCC M-30	0.00000	0.00000	215.00000	

1 Signed Hand Copy and Soft Copy (in Excel) of provided MIS is enclosed.
2 Up-to-date Physical Progress has been updated in MIS.

DAO
RWD, Works Division, Mahnar

Executive Engineer
RWD, Works Division, Mahnar

FORM GFR -19 -A

(see Govt. of India's decision (i) below rule 150)

Form of Utilisation Certificate upto 29.07.2024

Rural Road Maintenance policy-2018

PIU:- R.W.D. Works, Division , Mahnar

Sl. No.	Name of Scheme	Sanction No.& Date with amount (in Rs. Lakh)	Amount Received (in Rs. Lakh)	Particulars
1	2	3	4	5
1	Construction of Road Under Rural Road Maintenance policy-2018	12980.29204	12980.29204	Certified that out of Rs.12980.29204 Lakh received till date in favour of Ex-Engineer, R.W.D. Works Division, Mahnar a sum of Rs. 12620.67707 Lakh has been utilized for the purpose of Rural Road Maintenance policy-2018 Scheme as given in the margin for which it was sanctioned and that the balance of Rs. 359.61497 Lakh remaining unutilized at the end of the period under the time of completion.
		12980.29204	12980.29204	

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the propose for which it was sanctioned.


Kind of Checks Exercised :-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/Superintending Engineer
- (iii) Construction materials have been tested.
- (iv) Measurements have been recorded in the MB's and test check conducted by the Assistant
- (v) All other codal formalities have overserved

3 Physical Progress Achieved.


- (i) Construction of Bridge Works
- (ii) Construction of Piling Works.


29/7/24
Divisional Account Officer
Rural works Department
Works Division, mahnar


29/7/24
Executive Engineer
Rural works Department
Works Division, mahnar
Recd 29.7.24

File :D:\BUMP\santoshi\29072024\santoshi.xlsx, Section No. :54, Eqn : $Y = 0 \cdot X^2 + 0.860 \cdot X + 622.7$

Name of Customer : Santoshi Singh, Name of Work/ Road : Kargil Gate Se Kutubpur Sangat Tak Durga Mandir Tak, Lab Job



4/29/24
29/7/24
JG

1/29/24
29/7/24
JG

Contractor Name:- Santoshi Singh

Work Name:- Kargil Gate Se Kutubpur Sangat Tak Durgamandir Tak

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR	IRI, TEGORY	Latitude	Longitude	Event	
29/7/24	11:23:25	54	0.1	390	10.1	3900	3976 G	25.621893	85.383626	Normal	Y = 0 * X ^ 2 + 0.360 * X + 622.7 X = 2700 Y = 2944
29/7/24	11:24:1	54	0.1	340	10.1	3400	3546 G	25.621267	85.383442	Normal	
29/7/24	11:24:36	54	0.1	230	10.1	2300	2600 G	25.619957	85.383306	Normal	(R) RURAL ROAD Good Average Poor <4000 4001-5000 >5001
29/7/24	11:25:11	54	0.1	230	30.3	2300	2600 G	25.618532	85.383076	Normal	
29/7/24	11:25:11	54	0.1	340	10.1	3400	3546 G	25.617902	85.383025	Normal	
29/7/24	11:25:11	54	0.1	370	10.1	3700	3804 G	25.61698	85.382869	Normal	
29/7/24	11:25:11	54	0.1	330	30.3	3300	3460 G	25.614955	85.382476	Normal	
29/7/24	11:25:11	54	0.1	260	10.1	2600	2858 G	25.61372	85.382472	Normal	
29/7/24	11:25:46	54	0.1	350	10.1	3500	3632 G	25.613164	85.382539	Normal	
29/7/24	11:26:22	54	0.1	340	10.1	3400	3546 G	25.612987	85.3812971	Normal	
29/7/24	11:26:22	54	0.1	260	10.1	2600	2858 G	25.611538	85.38119	Normal	
29/7/24	11:27:32	54	0.1	390	10.1	3900	3976 G	25.610732	85.383926	Normal	
29/7/24	11:28:0	54	0.1	390	10.1	3900	3976 G	25.610022	85.383775	Normal	
29/7/24	11:28:8	54	0.1	340	10.1	3400	3546 G	25.609905	85.382911	Normal	
29/7/24	11:28:8	54	0.1	260	10.1	2600	2858 G	25.610057	85.381302	Normal	
29/7/24	11:28:43	54	0.1	390	10.1	3900	3976 G	25.610031	85.381209	Normal	
29/7/24	11:29:18	54	0.1	260	10.1	2600	2858 G	25.610006	85.382901	Normal	
29/7/24	11:29:18	54	0.1	350	10.1	3500	3632 G	25.609942	85.383537	Normal	
29/7/24	11:30:0	54	0.1	230	10.1	2300	2600 G	25.610371	85.383789	Normal	
29/7/24	11:30:29	54	0.1	260	10.1	2600	2858 G	25.611431	85.384084	Curve	
29/7/24	11:31:4	54	0.1	390	10.1	3900	3976 G	25.613164	85.382539	Normal	
29/7/24	11:31:4	54	0.1	260	10.1	2600	2858 G	25.609905	85.382911	Normal	
29/7/24	11:31:4	54	0.1	350	10.1	3500	3632 G	25.611538	85.38119	Normal	
29/7/24	11:31:39	54	0.1	260	10.1	2600	2858 G	25.619957	85.383306	Normal	
29/7/24	11:32:15	54	0.1	270	10.1	2700	2944 G	25.61372	85.382472	Normal	
29/7/24	11:32:15	54	0.1	230	10.1	2300	2600 G	25.613164	85.382539	Normal	
29/7/24	11:33:0	54	0.1	340	10.1	3400	3546 G	25.619957	85.383306	Normal	
29/7/24	11:33:25	54	0.1	230	10.1	2300	2600 G	25.618532	85.383076	Normal	
29/7/24	11:34:0	54	0.1	390	10.1	3900	3976 G	25.611431	85.384084	Normal	
29/7/24	11:57:0	54	0.051	270	10.1	2700	2944 G	25.609942	85.383537	Normal	

Machine 468

IRI Value 3288

dy
29/7/24

dy
29/7/24