

Baraon More Ke Pass to Hat Pokhah.

NDB (Bricks)

Schedule XLV-Form No. 134

PIRO

DIVISION

PIRO

SUB-DIVISION

Contractor Name $\rightarrow$ *Shri Sanjay Kumar.*

Measurement Book

Agg. No. $\rightarrow$ 48/SBD/mmsy/NDB-Bricks.

NO. $\rightarrow$ 431

4th Year maintenance bill

31

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- Baran more ke pati					
to hot pokhar.					
Agency:- Sri Saajay Kumar.					
Agg no:- 48/SB/11/MSY/ NDB					
brick 12018-19					
date of actual completion:-					
date of n/s:-					

① Restoration of drain cuts-etc.

6 x 4 x 1.80 x 0.30 =	12.96m ³
5 x 4 x 2.0 x 0.30 =	12m ³
2 x 4 x 1.20 x 0.30 =	2.88m ³
2 x 5 x 1.10 x 0.30 =	3.30m ³
2 x 4 x 1.70 x 0.30 =	2.88m ³
2 x 7 x 1.0 x 0.30 =	4.20m ³
	T = 38.22m ³
	4' = 28.76m ³

② Making up to beam / shoulder-etc.

2 x 30 x 1.10 =	66m ²
3 x 30 x 1.10 =	99m ²
	T = 156m ²

③ Repair of hot filled with 7mm

W.B.M. ——— etc	
10 x 5 x 1.20 x 0.075 =	4.50m ³
10 x 6 x 1.20 x 0.075 =	5.40m ³
8 x 6 x 1.10 x 0.075 =	3.96m ³

Continuation

Abstract of cost.

33

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of rain cut-off					
Qty: - 28.76 m ³			Tm B.	P-31	✓
@ Rs: - 365.25/m ³				Rs: - 10,504 = ∞	
② Making up to berm/					
Shoulder				E/I	
Qty: - 156 m ²			Tm B.		
				P-31	✓
@ Rs: - 54.14/m ²				Rs: - 8448 = ∞	
③ Repair of pot hole filled					
with 75 mm W.B.M. - E/I					
Qty: - 23.44 m ³			Tm B.		
				P-32	✓
@ Rs: - 359.93/m ³				Rs: - 8436 = ∞	
④ Patch repair over bituminous					
Surface with 20 mm					
M.S. - E/I					
Qty: - 12 24.68 m ²					
			Tm B.	P-32	✓
Limit: - 23.44 m ²					4993 = ∞
@ Rs: - 213.04/m ²				Rs: - 8436 = ∞	
⑤ Cutting of branches of					
trees and shrub - E/I					
Qty: - 107.48 m ³			Tm B.	P-32	✓
@ Rs: - 107.48/m ³				Rs: - 107 = ∞	
				Total Rs: - 32,488 = ∞	
below 10%.				@ Rs: - 3249 = ∞	

Continuation Total Rs: - 29,239 = ∞

Sd/-
10/2/24
J.E

Ck
6/2/24
A.C