

5th Year maintenance

78

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: Repair & Dayal petrol pump to Deh Tolavada					
mm GSY					
2. Name of Agency: Ramesh Thakur patara, pier (mms)					
3. Agreement No: 735BD/2018-19					
4. Actual dt. of completion: 10.05.2019					
- measurement as below -					
① Restoration of drain cuts					
① will soil - double					
24 6435.00			0.30 + 0.40	0.30	
			2		= 34.38 m ²
24 3430.00			0.30 + 0.40	0.30	
			2		= 18.20 m ²
24 1710.50			0.30 + 0.40	0.30	
			2		= 2.205
14 20.80			0.30 + 0.40	0.30	
			2		= 2.184
14 20.70			0.30 + 0.40	0.30	
			2		= 2.235
14 18.90			0.30 + 0.40	0.30	
			2		= 2.04
14 20.50			0.30 + 0.40	0.30	
			2		= 2.152
24 3430.00			0.30 + 0.40	0.30	
			2		= 18.90
24 4430.00			0.30 + 0.40	0.30	
			2		= 25.20
24 3430.00			0.30 + 0.40	0.30	
			2		= 18.90
24 20.50			0.30 + 0.40	0.30	
			2		= 4.305
					Qty = 97.02 m ²
					say Qty = 96.05 m ²
② maintenance of garden					
shoulder - double					

Continuation
14 20.50 x 0.70 = 10.45 m²
C.V Qty = 10.45 m²
7.175
P. 7.175

83
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B.F. 12	3372 = w
⑤ Bitumens & layers of hot applied thermoplastic compound 2.5mm thick - du 212					
Qty = 270.80 m ² wide					
				Temp Page ⑧	
Item No ⑤					
@ Rs 770 = 48/m ² - b					185532 = w
⑥ 157 maintenance Bitum pipe culvert - du 212					
Qty = 4.0 m wide					
				Temp Page ⑧	
Item No ⑥					
@ Rs 1131 = 67/each - b					4527 = w
⑦ 157 maintenance of slab type culvert - du 212					
Qty = 2.0 m wide					
				Temp Page ⑧	
Item No ⑦					
@ Rs 2336 = 82/each - b					4674 = w
⑧ 1511 maintenance of 20m x 2m 1st - du 212					
Qty = 1.204 Km = 1.20 Km					
				Temp Page ⑧	
Item No ⑧					

Rs 728 = 56 of 11/11/2024
 10.05.2024
 J.F.
 16/5/24
 26
 Rs 874 = w
 Rs 318979 = w