

Shyam Mainbama

70

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) N/w - 000 to Baguli					
Agency - M/S Kumari					
Construction.					
Agg. No - 01 N M 45 / S B D /					
				2016-2017	
Actual date of comp.					
				22/01/2018	

1) Restoration of Rain Cuts.

40x	5.00x	1.00x	0.30=	60.00m ³
21x	3.00x	1.00x	0.30=	18.90m ³
17x	5.00x	1.00x	0.30=	25.50m ³
60x	6.00x	1.00x	0.30=	108.00m ³
54x	4.00x	1.50x	0.30=	61.20m ³
18x	6.50x	1.00x	0.25=	29.25m ³
51x	3.00x	1.25x	0.30=	57.37m ³
75x	6.00x	1.50x	0.30=	202.5m ³
				562.72m ³

2) Maintenance of Mune Pipe

				20.00m ³
--	--	--	--	---------------------

3) Making up loss of Material

2x	10x	30.00x	1.875=	1125.00m ³
2x	18x	30.00x	1.875=	2025.00m ³
2x	40x	30.00x	1.875=	4500.00m ³
2x	9x	30.00x	1.875=	1012.50m ³

Continuation 506.25m³
= 3656.25m³

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4) Patch repair on					
already.					
=	55	1.24	m		
or 125 = 14/100 - 107					569 =
5) Repair of Post					
Reels by round Thine					
=	55	1.24	m		
from 8 = 56/100 - 114					967 =
					603 147 = 00
less 10% written Agg.					
					60,315 = 00
					542832 = 00

Tab.
02/02/23

Continuation