

Continuation

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
Atstand of cut					
18 year maintenance B.M					
(115-1)	Restoration of				
	rain cut with cut				
P-74	24m-115-1				
105.574 m ³ @	404.66/m ²				42658-
(215-2)	makeup up of				
	Berm/shoulder				
P-75	24m-215-1				
307.69 m ² @	60.28/m ²				18540-
(315-311)	Pot repair with				
	on road surface				
P-75	24m-315-311				
25.64 m ² @	275.59/m ²				7066-
(415-741)	maintenance of				
	Hume pipe culvert				
P-76	24m-415-741				
1 Nos @	1168.58/ea				1167-
(515-711)	maintenance of				
	Slack culvert				
P-76	24m-515-711				
1 Nos @	2394.96				2395-

Continuation

71834-

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
(815.9) modern road					
P-76 24m 615.9					
0.21 km @ 1104.14 m					232
(415.11) modern of road					
P-76 24m 715.11					
0.25 km @ 641.92 m					160
(815.124) cutting of broadway					
P-76 24m 815.124					
3 Nos @ 113.64 m					341
(115.124) cutting of drains					
P-76 24m 915.124					
11 Nos @ 6.98 m					77
(1015.124) Temporary of area					
P-76 24m 1015.124					
2800 m ² @ 2.33 m ²					65
(1115.13) Block and culch					
Culch on protected way					
P-76 24m 1115.13					
21000 m ² @ 16.87 m ²					354
					73063 =
					731 =
Ad 14 Less =					8768
Ad 124 457 =					
					82562 =
Less 1579 Ad 16339					
					66223 =

Removal
30/5/24

Signature
6/5/24

6/5/24