

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: maintenance of Road					
Location: Mins, Besantokanjya					
Under contract (SC) for Bangalore					
Assy: Shri Suresh Singh					
Agreed: 32/2018-19					
Actual Date of completion: 9.5.19					
① Restoration of pavements / Besantokanjya					
					$2 \times 10 \times 30.00 \times 0.50 \times 0.30 = 90.00 \text{ m}^3$
					Total = <u>90.00</u>
② Grading up of Besantokanjya / Khondker					
					$2 \times 10 \times 30.00 \times 0.50 = 300.00 \text{ m}^3$
					$2 \times 3 \times 30.00 \times 0.50 = 90.00$
					Total = <u>390.00</u>
③ Repair of pavements with 15% concrete					
					$4 \times 3.00 \times 2.50 = 30.00 \text{ m}^2$
					$1 \times 16.84 \times 3.00 = 50.52 \text{ m}^2$
					Total = <u>80.52</u>
④ Patch repair over bituminous surface with 20% concrete					
					$4 \times 3.00 \times 2.50 = 30.00 \text{ m}^2$
					$1 \times 16.84 \times 3.00 = 50.52 \text{ m}^2$
					Total = <u>80.52</u>
⑤ Maintenance of CIP works (HPC)					
					$1 \times 2 \text{ N.M.} = 2 \text{ N.M.}$
					Total = <u>2 N.M.</u>

ABSTRACT

41

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of road works vide item no. ① V.P. No. ④①					
Qty = 90.00 m ³ @ 352.21/m ³					28242
Cost 80.19 m ³					
② Dressing of shoulders etc. vide item no. ② V.P. No. ④①					
Qty = 390.00 m ² @ 51.71/m ²					19983
Cost 386.44 m ²					
③ Repair of potholes with bitumen vide item no. ③ V.P. No. ④①					
Qty = 80.52 m ² @ 253.97/m ²					20398
④ Patch repair over bitumen vide item no. ④ V.P. No. ④①					
Qty = 80.52 m ² @ 190.02/m ²					15298
⑤ Mains of CID works (HBC) vide item no. ⑤ V.P. No. ④①					
Qty = 8 Nos. @ 1104.25/ea					22092
					Total = 86130
					⑥ less 0.50% = 431
					Total = 85699
					888
					812/23
					JE
Material Statement-					
① Bitumen - 80.19 m ³					
② Stone chips - 2.17 m ³					
③ Bitumen S-90 - 188.42 kg					
					888
					812/23
					JE

Continuation

4th year maintenance VSM

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of house: Telhara on road Beran to Kanjar.					
Agency: Shri Suresh Singh					
Ass no: 32/2018-19					
Actual date of completion: 9.5.19					
① Restoration of water cistern - T.S.					
					$2 \times 11 \times 30.00 \times 0.45 \times 0.30 = 89.10 \text{ m}^3$
				Total =	<u>89.10 //</u>
② making up kerbs/shoulder - T.S.					
					$2 \times 15 \times 30.60 \times 0.50 = 459.00 \text{ m}^2$
				Total =	<u>459.00 //</u>
③ Repair of pot holes with stone & concrete - T.S.					
					$8 \times 4 \times 2.50 = 80.00 \text{ m}^2$
					$1 \times 9.00 \times 3.04 = 27.36 //$
				Total =	<u>107.36 //</u>
④ patch repair over bitumen and surface with 20mm sand - T.S.					
					only stone & item ③ = 107.36 m^2
				Total =	<u>107.36 //</u>
⑤ maintenance of CD works (H.P.) - T.S.					
					$1 \times 2 \text{ NAP} = 2 \text{ NAP}$
				Total =	<u>2 NAP //</u>
					88
					818/25
					55

