

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1st year maintenance					
name of work. point of					
road from. Kohna Bagor to					
Bahriger 10/9					
agency - Sri Vijayal bin					
Agreement No - 88533/mmbv/01-22					
Actual Completion. 07.04.2022					
Revised Entry					
1) Restoration of 2017					
with soil					
— do —					
4 x 3.60 x 0.80 x 0.30 = 3.46					
3 x 5.40 x 0.70 x 0.30 = 3.40					
9 x 2.80 x 0.90 x 0.30 = 6.80					
6 x 4.10 x 0.75 x 0.30 = 5.54					
5 x 5.20 x 1.10 x 0.30 = 8.58					
Total					27.78
2) point of earthwork					
2 shoulders - do					
2 x 6 x 5.80 x 0.90 = 62.64					
2 x 8 x 4.60 x 0.70 = 51.52					
2 x 6 x 5.15 x 0.65 = 40.12					
Total					154.28
3) point of earthwork					

ation